



METCALF SEPTIC SERVICES

+18282848320

metcalfsepticpumping@gmail.com

<https://www.metcalfseptic-service.com/weaverville-septic-service>



SEPTIC INSPECTION REPORT

38 Forest Knoll Dr
Weaverville, NC 28787

Cameron Home Inspections

06/30/2026



Inspector

Aiden Metcalf

Aiden Metcalf

NCOWICB 11574I

+18282848320

metcalfsepticpumping@gmail.com

TABLE OF CONTENTS

1: Overview	5
2: Pipe to tank	6
3: Septic Tank	6
4: Pipe after tank	10
5: Drain Field	11
6: Final Notes	11

(HTML version only) To view the summary, click on the 'Summary' tab above or click 'PDF' (upper right tab) and then 'Summary'.

The summary page is not the entire report. The complete report may include additional information of interest or concern to you. It is strongly recommended that you promptly read the complete report.

- A certified On-site Waste Contractor or 'septic repair company' should be consulted for further evaluation and repair for all defects and recommendations in the report to ensure proper operation and to extend the service life of the septic system. It is recommended to have the septic tank pumped every 3 to 5 years.

Types of Comments:



- **For Your Information**



- **Recommendation or
Maintenance**



- **Repair or Defect**



DEFECT

-
- ⊖ 3.1.1 Septic Tank - Exterior Components: Grading/surface observations/defect(s)
 - ⊖ 3.2.1 Septic Tank - Interior Components: Inlet/Outlet Pipe Defect(s)
 - ⊖ 4.1.1 Pipe after tank - Pipe after tank: Pipe after tank defects

1: OVERVIEW

		IN	NI	NP	D
1.1	General Information	X			
1.2	Type of system	X			
1.3	Clearances and Setbacks	X			

IN = Inspected NI = Not Inspected NP = Not Present D = Deficiencies

Information

General Information:
Documentation

Not found

General Information: # of
Bedrooms per Operations Permit

Undetermined

Type of system: Tank material

Concrete



General Information: Type of
water supply

Private well

General Information: House
occupied at time of inspection?

Undetermined

Clearances and Setbacks:

Distance from water line

More than 50' (good)

General Information: # of
Bedrooms per MLS Listing

4

Type of system: Designed for

Residential

Clearances and Setbacks:

Distance from house

More than 15' from basement
(good)



Clearances and Setbacks:
Distance from property line

More than 10' from property line
(good)

Clearances and Setbacks:
Distance from well

More than 50' (good)



Well location

2: PIPE TO TANK

		IN	NI	NP	D
2.1	Pipe from house to tank	X			

IN = Inspected NI = Not Inspected NP = Not Present D = Deficiencies

Information

Inspection method

From surface only

Clean out location

None observed

Pipe material

PVC



Diameter of pipe

4 inches

Approx. length from clean out to the tank

None

3: SEPTIC TANK

		IN	NI	NP	D
3.1	Exterior Components	X			X
3.2	Interior Components	X			X

IN = Inspected NI = Not Inspected NP = Not Present D = Deficiencies

Information

System requires certified operator

No

Tank material

Concrete

Tank size

1000 gallons



Lid size(s)

24x24"

20x20 concrete lids

Effluent filterNot present - tank installed before
1998**Flow and Level**Confirmed sewage enters tank
(inflow), Confirmed effluent leaves
tank (outflow)**Scum level**Less than 2 inches, In outlet
compartment**Sludge level**between 2-4 inches, In the inlet
compartment**Percentage of solids in the tank**

Less than 20% (Good)

**Freeboard space**Greater than 9 inches of
freeboard (Good)**Tank lids material**

Plastic


**Access risers**

Present, Plastic



Inlet Pipe

PVC

**Outlet T**

Concrete trap with pvc outlet

**# of Compartments**

2 (inlet and outlet compartments)

**Baffle wall**

Concrete, Intact



Septic tank pumped



Yes - all tank compartments were pumped during inspection



Condition of septic tank

Good

A septic tank is an underground wastewater treatment system commonly used in areas without centralized sewer systems. It typically consists of a large, watertight container buried in the ground that receives and processes household wastewater from toilets, sinks, showers, and appliances. The system separates solids from liquids, allowing bacteria to break down organic matter before effluent is distributed into a drain field for final treatment and absorption.




Deficiencies

3.1.1 Exterior Components

GRADING/SURFACE OBSERVATIONS/DEFECT(S)

Rock walkway over top of septic tank

Grading repairs may be needed to prevent root damage and/or water infiltration into the tank. A septic contractor or landscaper can be consulted for repair.



3.2.1 Interior Components

INLET/OUTLET PIPE DEFECT(S)

Too high, Outlet Pipe

The outlet pipe has settled causing it to be higher than it should be.




4: PIPE AFTER TANK

		IN	NI	NP	D
4.1	Pipe after tank	X			X

IN = InspectedNI = Not InspectedNP = Not PresentD = Deficiencies

Information

Overview Photos/Videos



Pipe material
PVC

Approx. diameter of the pipe
4 inches

Approx. length
Less than 25 feet

Distribution Box Found?
None found



Pipe after tank location

Deficiencies

4.1.1 Pipe after tank

PIPE AFTER TANK DEFECTS

Pipe offset/disconnected

Areas of the pipe after tank was observed to be offset or disconnected and could prevent proper flowing of the wastewater to the drain field. Refer to a septic contractor for repairs and maintenance.

Defect



5: DRAIN FIELD

		IN	NI	NP	D
5.1	Drain Field Lines	X			

IN = Inspected NI = Not Inspected NP = Not Present D = Deficiencies

Information

Photos/Videos	Type of drain field Type: Gravity (most common), Material: undetermined	# of drain field lines Undetermined
Total length of drain field lines Undetermined	Drain field lines Delivery of effluent confirmed (good)	Downspout Locations Downspouts away from drain field

Limitations

Information

NOTES AND LIMITATIONS

Visually inspected from surface only and with metal probe

6: FINAL NOTES

Information

Road/Driveway conditions to property

Good/Accessible, Paved

Final Notes

This is the end of the septic inspection report provided by Metcalf Septic Services.

We strive to provide clear and comprehensive details about your system in every report. If there are any details that you have questions or concerns about, do not hesitate to reach out to us at anytime.

If repairs or quotes are needed for defect items found in the report, we now offer quotes for all levels of septic repairs. Contact us for any questions or repair estimates.