## **USED VEHICLE INSPECTION REPORT**



**ADESA Wisconsin** W 10415 S.R. 33 Portage, WI 53901 Phone: (608) 742-8245 Fax: (608) 742-4415

Company

Name: CitiFinancial Auto

Customer Number: BX001

Cat Code:

Client Unit ID: 4536228201 Lessee/Borrower:

Vehicle Type: Repossession
Arrival Date: 04/16/2009 12:00 AM

Stock Number: 61470 Lot Location:

License:

**Rental Account:** 

License State:

		Ttoma.		2.00.100 01410	•	
VIN	Year	Make	Model	Series Or	Doors	Lift
	E	Body Style	Trim	Truck Dsc	#P	Gate
J T J B T 2 0 X 0 5 0 0 8 1 9 8	3 05 LEXUS		GX470		4	N
	UTILITY				5	
Mileage Odo Type Fuel DT	Transmission	Engine	Exterior Col		el Base	Mats
7 0 0 8 5 Digital 6 1/8 N	Automatic	4.7L V8 DOHC Gas		Grey / Leather		N
			Code:	Code:		
Sound Roo AM/FM/Cass/CD Power S				Equipment: Air Type:Air		
Alvi/Fivi/Cass/CD Fower's	ouii			Conditioning,Airbag Front Lo Right,Brake Type:ABS,CD I		
				Control,Drive Train:4x4,Eng		
				Cylinder Gas,Engine Type:(		5.0
				Lights,Heated Seats:Driver		enger I
No.	111/	<i>(</i>		Running Board, Memory Sea		inger,L
		—, <i>9</i> /-		Locks, Power Mirrors, Power		Power
		\ ( )		Windows,R Running Board,		••
				Equip:AM/FM/Cass/CD,Rea		Remote
	1 ( 5PE)	$\rightarrow$		Entry,Roof Luggage Rack,R		
				Sun, Seat Covering Type:Le		
Michelin 7/32"	7/32" Miche	elin		Options:Bucket,Seat:Power		
				Passenger,Spare Tire,Spare	e Wheel,T	elscping
				Steer Whl, Tilt Wheel, Tire		
				Brand:Michelin,Trailer Hitch		sion
				Type:Automatic,Wheel Type	e:Alloy	
	_					
				Keys:		
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~					Trunk 🗍	Alarm
		<del></del>	7	Ignition Code	_	
				Master: Valet: Mobilize	er: Wall	et:
				Seating Configuration:		
Michelin 8/32"	7/32" Mid	chelin	\$100.00			
			_			
Total Chargeable Damage:	\$150.00		Total Non-Charge	able Damage: \$0.00		

Total Chargeable Damage: \$150.00					То	tal Non-	-Charge	able Dama	ge:	\$0.00		
Damage Desc.	Damage Action	Y D	T D	S A	Airbrush Amount	Body Hours	Ref Hours	Labor Amount	Parts	PDR Amount	Total Charges	C/ NC
FRONT Bumper Cover												
Pitted	Repair				100.00						100.00	С
REAR Bumper Cover												
Chipped less than 1 inch	Repair				50.00						50.00	С
RF DR Panel												
Previous Repair	Report											NC
Totals					150.00	0.00	0.00	0.00	0.00	0.00	150.00	

Pickup Date: 04/16/2009 12:00 AM

Return Date: Acceptance Date: Reject Codes: **Condition: Grade 4-Clean** 

Statements:

Mileage of Last Service:

Last Service Date:
Mechanical Rating:
General Condition: Good

Certification Candidate:
Appraisal Required:

File Claim:

Request Previous RO:

Deductible Amount: \$0.00

De-Identify:

Comments: Possible GOLD. F Bumper full, full touch up. Maint. Req. light is on


Internet Candidate:

Interior Condition: Average

Drivable: Y

Recondition Instructions: Complete Detail





Body Shop Total: 150.00
B/S Parts Total: 0.00
PDR Total: 0.00
Glass Total: 0.00
Tires Total: 0.00
Mechanical Total: 0.00
Recon Total: 0.00

Misc: 0.00 Total: 150.00









Title Received:	04/28/2009	Acceptance Date:	
Account Signature:		Date:	05/05/2009

**Detail Fees Not Included** 

Inspection Report Prepared by: Lawrence Asher Date: 04/17/2009 09:38:07 AM