


RFI-002 - Manhole Provision Excessive - Stormwater



Excessive manhole
usage on road radii

Review an alternative constructable solution to this arrangement.
there are 24 manholes installed within one bend in the road - totally excessive.
An alternative solution can be proposed with a formed GRP radiused section for
the respective pipework.
The principle of installing a manhole in this location appears to be the radius of
the pipework and not for access.

Recommendation - Revise to ensure

- Time and Cost saving
- Aesthetic Improvement of the streetscape which will foul future public realm
and landscape design, potentially streetlighting and security impact.
- utilise closed concrete channel - customised radius section and/or pipework