
SHEET INDEX

HEET#	SHEET DESCRIPTION
S1.0	COVER SHEET
S1.1	EAST AND WEST TANK PLAN
S2.1	EAST TANK ELEVATIONS
S2.2	WEST TANK ELEVATIONS
S3.1	CONCRETE REPAIR DETAILS





Water Treatment Plant 3 (WTP 3) East Dome and Aerator and Miscellaneous Improvements 2775 SR 580, Clearwater, Florida 33761



CITY OFFICIALS

Frank Hibbard
Mark Bunker
Kathleen Beckman
David Allbritton
Hoyt Hamilton
Jon Jennings

Mayor Councilmember Councilmember Councilmember Councilmember City Manager


Tara L. Kivett, P.E. City Engineer


Approved For Construction

CITY ENGINEER Tara L. Kivett, P.E. #86611

Date Approved

City Project No. 20-0012-UT City Plan Set No. 2020026





GENERAL REPAIR NOTES:

ELEMENTS/SURFACES.

SPECIFIC REPAIR NOTES:

(BOTH METAL AND CONCRETE SURFACES).

N-1 TREAT CRACK PER SPECIFICATION 09 96 00.

PER SPECIFICATION 03 72 00.

LEGEND:

INTERFACE. REFER TO SPECIFICATION 07 92 00.

REFER TO SPECIFICATION 01 01 00 FOR GENERAL SUMMARY OF WORK FOR PROJECT.

4 REFER TO DETAILS 1 THRU 5 ON SHEETS S3.1 FOR STANDARD CONCRETE REPAIR DETAILS.

5 PERFORM SURFACE PREPARATIONS AND COAT THE TANK AND ASSOCIATED EQUIPMENT PER SPECIFICATION 09 96 00, INCLUDING ALL EXISTING COATED INTERIOR AND EXTERIOR SURFACES

N-2 RESTORE HATCH TO ORIGINAL CONDITION. REFER TO SPECIFICATION 03 72 00 AND 5/S3.1.

N-8 REPAIR AREAS OF CONCRETE DAMAGE, SUCH AS SPALLS AND DELAMINATING CONCRETE,

N-5 REMOVE EXISTING JOINT SEALANT AND REPLACE WITH NEW JOINT SEALANT AT TANK FLOOR TO WALL

N-6 REPAIR AREAS OF CONCRETE DAMAGE AROUND OVERFLOW DETAIL. REFER TO SPECIFICATION 03 72 00 AND

N-3 TREAT AREAS OF DELAMINATING EXISTING COATING PER SPECIFICATION 09 96 00.
N-4 REMOVE EXISTING GASKET OF MANWAY COVER AND REPLACE WITH NEW GASKET.

N-7 TREAT AREAS OF MINOR SURFACE DEFECTS PER SPECIFICATION 09 96 00.

N-# - INDICATES SPECIFIC REPAIR NOTE. REFER TO ABOVE FOR SPECIFIC REPAIR NOTES.


3 REPAIR AREAS OF CONCRETE DAMAGE. REFER TO SPECIFICATION 03 72 00.

2 REMOVE THE EXISTING COATING FROM ALL INTERIOR TANK SURFACES PER SPECIFICATION 09 96 00


(BOTH METAL AND CONCRETE) AND ALLOW ENGINEER TO REVIEW EXISTING CONDITION OF UNDERLYING

E1 EAST TANK ROOF PLAN NOT TO SCALE

E2 EAST TANK INTERIOR PLAN S1.1 NOT TO SCALE







W2 WEST TANK INTERIOR PLAN S1.1) NOT TO SCALE

For Bid

DIFFERENCE OF THE ENGINEER'S KNOWLEDGE, THE PLANS AND SPECIFICATIONS COMPLY WITH THE APPLICABLE MINIMUM BUILDING CODES

3434 colwell avenue suite 100, tampa, florida 33614 telephone: 813.908.7203 fax: 813.931.5200 email: info@billerreinhart.com

State of Florida Certificate of Authorization No. 9149

TO THE BEST OF THE ENGINEER'S KNOWLEDGE, THE PLANS AND SPECIFICATIONS COMPLEY WITH THE APPLICABLE MINIMUM BUILDING CODES

BRIAN E. WALTER
FL. P.E. NO. 66538

THIS ITEM HAS BEEN DIGITALLY SIGNED AND SEALED. PRINTED COPIES OF THIS DOCUMENT ARE NOT CONSIDERED SIGNED AND SIGNED AND THE SIGNATURE MUST BE VERIFIED ON ANY ELECTRONIC COPIES

TO THE BEST OF THE ENGINEER'S KNOWLEDGE, THE PLANS AND SPECIFICATIONS COMPLY WITH THE APPLICABLE MINIMUM BUILDING CODES

BRIAN E. WALTER
FL. P.E. NO. 66538

THIS ITEM HAS BEEN DIGITALLY SIGNED AND SEALED. PRINTED COPIES OF THIS DOCUMENT ARE NOT CONSIDERED SIGNED AND SIGNED AND THE SIGNATURE MUST BE VERIFIED ON ANY ELECTRONIC COPIES

REVISION

BY DATE

CITY OF CLEARWATER, FLORIDA ENGINEERING DEPARTMENT 100 S. MYRTLE AVE. CLEARWATER, FL 33756 NVESTIGATE BEFORE YOU EXCAVATE

OALL 811

SUNSHINE STATE

ONE CALL

OF FLORIDA

www.callsunshine.com

(800) 432-4770

MIN. 48 HOURS

BEFORE YOU EXCAVATE

Water Treatment Plant 3 (WTP3)
East Dome and Aerator and Miscellaneous Improvements
2775 SR 580, Clearwater, Florida 33761
EAST AND WEST TANK PLANS

	, , ,		
NAME: S1.1	FIELD BOOK: N/A	SURVEYED BY: N/A	SCALE: VERT. SEE PLAN
RACT NO.: 20-0012-UT	DATE DRAWN: 10-08-21	DRAWN BY: R.M.	HORIZ. SEE PLAN
No.: 20 –222	DESIGNED BY: B.W.	CHECKED BY: B.W.	SHEET NO.: X OF X
PROVED FOR ISTRUCTION			

CITY ENGINEER TARA L. KIVETT, P.E.

EAST TANK ELEVATIONS

GENERAL REPAIR NOTES:

- 1 REFER TO SPECIFICATION 01 01 00 FOR GENERAL SUMMARY OF WORK FOR PROJECT.
 2 REMOVE THE EXISTING COATING FROM ALL INTERIOR TANK SURFACES PER SPECIFICATION 09 96 00
- 2 REMOVE THE EXISTING COATING FROM ALL INTERIOR TANK SURFACES PER SPECIFICATION 09 96 00 (BOTH METAL AND CONCRETE) AND ALLOW ENGINEER TO REVIEW EXISTING CONDITION OF UNDERLYING ELEMENTS/SURFACES.
- 3 REPAIR AREAS OF CONCRETE DAMAGE. REFER TO SPECIFICATION 03 72 00.
- 4 REFER TO DETAILS 1 THRU 5 ON SHEETS S3.1 FOR STANDARD CONCRETE REPAIR DETAILS.
 5 PERFORM SURFACE PREPARATIONS AND COAT THE TANK AND ASSOCIATED EQUIPMENT PER SPECIFICATION 09 96 00, INCLUDING ALL EXISTING COATED INTERIOR AND EXTERIOR SURFACES (BOTH METAL AND CONCRETE SURFACES).


SPECIFIC REPAIR NOTES:


- N-1 TREAT CRACK PER SPECIFICATION 09 96 00.
- N-2 RESTORE HATCH TO ORIGINAL CONDITION. REFER TO SPECIFICATION 03 72 00 AND 5/S3.1.
- N-3 TREAT AREAS OF DELAMINATING EXISTING COATING PER SPECIFICATION 09 96 00.
 N-4 REMOVE EXISTING GASKET OF MANWAY COVER AND REPLACE WITH NEW GASKET.
- N-5 REMOVE EXISTING JOINT SEALANT AND REPLACE WITH NEW JOINT SEALANT AT TANK FLOOR TO WALL
- INTERFACE. REFER TO SPECIFICATION 07 92 00.


 N-6 REPAIR AREAS OF CONCRETE DAMAGE AROUND OVERFLOW DETAIL. REFER TO SPECIFICATION 03 72 00 AND
- 4/53.1.
 N-7 TREAT AREAS OF MINOR SURFACE DEFECTS PER SPECIFICATION 09 96 00.
- N-8 REPAIR AREAS OF CONCRETE DAMAGE, SUCH AS SPALLS AND DELAMINATING CONCRETE, PER SPECIFICATION 03 72 00.


LEGEND:

N-# - INDICATES SPECIFIC REPAIR NOTE. REFER TO ABOVE FOR SPECIFIC REPAIR NOTES.





























EAST SECTOR ELEVATION
S2.1

SOUTHEAST SECTOR ELEVATION
S2.1

SOUTH SECTOR ELEVATION

S2.1)

SOUTHWEST SECTOR ELEVATION

S2.1

For Bid



THE BEST OF THE ENGINEER'S KNOWLEDGE, THE ANS AND SPECIFICATIONS COMPLY WITH THE			
APPLICABLE MINIMUM BUILDING CODES			
BRIAN E. WALTER FL. P.E. NO. 66538			
S ITEM HAS BEEN DIGITALLY SIGNED AND SEALED. PRINTED COPIES OF THIS DOCUMENT ARE NOT			
SIDERED SIGNED AND SIGNED AND THE SIGNATURE AUST BE VERIFIED ON ANY ELECTRONIC COPIES	REVISION	BY	DATE

CITY OF CLEARWATER, FLORIDA ENGINEERING DEPARTMENT 100 S. MYRTLE AVE. CLEARWATER, FL 33756



Water Treatment Plant 3 (WTP3)
East Dome and Aerator and Miscellaneous Improvements
2775 SR 580, Clearwater, Florida 33761
EAST TANK ELEVATIONS

	1 01	DIG	
IAME: S2.1	FIELD BOOK: N/A	SURVEYED BY: N/A	SCALE: VERT. SEE PLAN
ACT NO.: 20-0012-UT	DATE DRAWN: 10-08-21	DRAWN BY:	HORIZ. SEE PLAN
o.: 20 – 222	DESIGNED BY: B.W.	CHECKED BY: B.W.	SHEET NO.: X OF X
ROVED FOR			

WEST TANK ELEVATIONS

GENERAL REPAIR NOTES:


- 1 REFER TO SPECIFICATION 01 01 00 FOR GENERAL SUMMARY OF WORK FOR PROJECT. 2 REMOVE THE EXISTING COATING FROM ALL INTERIOR TANK SURFACES PER SPECIFICATION 09 96 00 (BOTH METAL AND CONCRETE) AND ALLOW ENGINEER TO REVIEW EXISTING CONDITION OF UNDERLYING
 - ELEMENTS/SURFACES.
- 3 REPAIR AREAS OF CONCRETE DAMAGE. REFER TO SPECIFICATION 03 72 00. 4 REFER TO DETAILS 1 THRU 5 ON SHEETS S3.1 FOR STANDARD CONCRETE REPAIR DETAILS.
- 5 PERFORM SURFACE PREPARATIONS AND COAT THE TANK AND ASSOCIATED EQUIPMENT PER SPECIFICATION 09 96 00, INCLUDING ALL EXISTING COATED INTERIOR AND EXTERIOR SURFACES (BOTH METAL AND CONCRETE SURFACES).


SPECIFIC REPAIR NOTES:


- N-1 TREAT CRACK PER SPECIFICATION 09 96 00.
- N-2 RESTORE HATCH TO ORIGINAL CONDITION. REFER TO SPECIFICATION 03 72 00 AND 5/S3.1.
- N-3 TREAT AREAS OF DELAMINATING EXISTING COATING PER SPECIFICATION 09 96 00. N-4 REMOVE EXISTING GASKET OF MANWAY COVER AND REPLACE WITH NEW GASKET.
- N-5 REMOVE EXISTING JOINT SEALANT AND REPLACE WITH NEW JOINT SEALANT AT TANK FLOOR TO WALL INTERFACE. REFER TO SPECIFICATION 07 92 00.
- N-6 REPAIR AREAS OF CONCRETE DAMAGE AROUND OVERFLOW DETAIL. REFER TO SPECIFICATION 03 72 00 AND
- N-7 TREAT AREAS OF MINOR SURFACE DEFECTS PER SPECIFICATION 09 96 00.
- N-8 REPAIR AREAS OF CONCRETE DAMAGE, SUCH AS SPALLS AND DELAMINATING CONCRETE, PER SPECIFICATION 03 72 00.

LEGEND:

N-# - INDICATES SPECIFIC REPAIR NOTE. REFER TO ABOVE FOR SPECIFIC REPAIR NOTES.



























W7 EAST SECTOR ELEVATION
S2.2



SOUTH SECTOR ELEVATION

SOUTHWEST SECTOR ELEVATION

S2.2

For Rid

3434 colwell avenue suite 100, tampa, florida 33614 telephone: 813.908.7203 fax: 813.931.5200 email: info@billerreinhart.com

TO THE BEST OF THE ENGINEER'S KNOWLEDGE, THE PLANS AND SPECIFICATIONS COMPLY WITH THE APPLICABLE MINIMUM BUILDING CODES BRIAN E. WALTER FL. P.E. NO. 66538 THIS ITEM HAS BEEN DIGITALLY SIGNED AND SEALED. email: info@billerreinhart.com

PRINTED COPIES OF THIS DOCUMENT ARE NOT

State of Florida Certificate of Authorization No. 9149

PRINTED COPIES OF THIS DOCUMENT ARE NOT

CONSIDERED SIGNED AND SIGNED AND THE SIGNATURE
MUST BE VERIFIED ON ANY ELECTRONIC COPIES REVISION

CITY OF CLEARWATER, FLORIDA ENGINEERING DEPARTMENT 100 S. MYRTLE AVE. CLEARWATER, FL 33756



Water Treatment Plant 3 (WTP3)
East Dome and Aerator and Miscellaneous Improvements 2775 SR 580, Clearwater, Florida 33761 WEST TANK ELEVATIONS

	1 01	DIG	
IAME: S2.2	FIELD BOOK: N/A	SURVEYED BY: N/A	SCALE: VERT. SEE PLAN
ACT NO.: 20-0012-UT	DATE DRAWN: 10-08-21	DRAWN BY:	HORIZ. SEE PLAN
o.: 20 – 222	DESIGNED BY: B.W.	CHECKED BY: B.W.	SHEET NO.: X OF X
ROVED FOR			

CITY ENGINEER TARA L. KIVETT, P.E.





FIGURE 1:

SURFACE PREPARATION WHEN CORRODED REINFORCEMENT IS ENCOUNTERED. REFER TO FIGURES 2 AND 3.



CORRODED BAR. UNDERCUT TO SOUND CONCRETE

FIGURE 2:

SURFACE PREPARATION WHEN CORRODED REINFORCEMENT IS ENCOUNTERED AT TOP BARS ONLY. REFER TO FIGURE 4





FIGURE 3:

SIGNACE PREPARATION WHEN CORRODED REINFORCEMENT

FIGURE 4:

SURFACE PREPARATION WHEN CORRODED REINFORCEMENT IS ENCOUNTERED AT TOP BARS ONLY.




NOTES FOR FIGURES 1-5:

- 1. EXPOSE CORRODED STEEL REINFORCEMENT UNTIL UNOXIDIZED, UNCORRODED STEEL WITH SOUND BOND TO THE EXISTING CONCRETE SUBSTRATE IS ENCOUNTERED.
- 2. CLEARANCE BETWEEN UNDERCUT STEEL REINFORCEMENT AND SOUND CONCRETE SUBSTRATE SHALL BE 3 MINIMUM OR 1 LARGER THAN THE LARGEST AGGREGATE IN THE CONCRETE REPAIR
- 3. THE CONTRACTOR SHALL PROVIDE ADEQUATE SHORING PRIOR TO CONCRETE DEMOLITION.

FIGURE 5:

SURFACE PREPARATION WHEN CORRODED REINFORCEMENT IS ENCOUNTERED AT TOP AND BOTTOM BARS.

SURFACE PREPARATION DETAILS



PLAN VIEW

BOUNDARY OF LOOSE AND

PLAN VIEW

OF SLAB


DELAMINATED CONCRETE

NOTE: RESTORE OVERFLOW DETAIL TO ORIGINAL DIMENSIONS, CONFIGURATION,

> OVERFLOW DETAIL


ETC. REFER TO SPECIFICATION 03 72 00.

4 OVERFLOW SCUPPER REPAIR DETAIL




ELEVATION & SECTION VIEW

2 GEOMETRY OF CONCRETE REPAIRS S3.1 SCALE: N.T.S.




RECOMMENDED LAYOUT





3 REINFORCING STEEL REPAIR — SECTION LOSS DETAIL



5 HATCH REPAIR DETAIL

For Bid



APPLICABLE MINIMUM BUILDING CODES **BRIAN E. WALTER** FL. P.E. NO. 66538 THIS ITEM HAS BEEN DIGITALLY SIGNED AND SEALED email: into@billerreinhart.com

State of Florida Certificate of Authorization No. 9149

PRINTED COPIES OF THIS DOCUMENT ARE NOT CONSIDERED SIGNED AND SIGNED AND THE SIGNATURE NOT CONSIDERED SIGNED SIGNED AND THE SIGNATURE NOT CONSIDERED SIGNED **REVISION**

CITY OF CLEARWATER, FLORIDA ENGINEERING DEPARTMENT 100 S. MYRTLE AVE. CLEARWATER, FL 33756

SUNSHINE STATE ONE CALL OF FLORIDA www.callsunshine.con (800) 432-4770 MIN. 48 HOURS BEFORE YOU EXCAVATE

Water Treatment Plant 3 (WTP3)

East Dome and Aerator and Miscellaneous Improvements 2775 SR 580, Clearwater, Florida 33761 CONCRETE REPAIR DETAILS

DWG NAME: S3.1	FIELD BOOK: N/A	SURVEYED BY:	SCALE: VERT. SEE PI
CONTRACT NO.: 20-0012-UT	DATE DRAWN: 10-08-21	DRAWN BY:	HORIZ. SEE PL
JOB NO.: 20-222	DESIGNED BY: B.W.	CHECKED BY: B.W.	SHEET NO.: X OF X
APPROVED FOR CONSTRUCTION	•		•
	CITY ENGINEER TARA L. I	(IVETT, P.E.	DATE