Exhibit B: Segment proof sheets (Berry test applied to Benton data)

Subset 532 | 2024 valid sales (county ratio code 100) | n=42 | Date range 2024-01-03 to 2024-07-17





Diagnostics (within-subset Berry test)

Median sale price:	$394,994
P10 to P90 price:	$370,295 to $430,887
Median ratio:	0.980
COD:	3.35%
PRD (approx):	1.0014
Controlled tilt beta (ln price):	-0.508 (p=3.3e-07, n=42)

What this shows: The countywide metrics can look neutral, but within this subset we observe statistically significant price-tilt after controlling for size, age, and condition. Negative beta means higher-priced sales have lower ratios within the subset (Berry-style vertical inequity signal).

Benton control levers to address within-segment tilt

- RES - Exterior Wall (matrix_id 3300, addition): Exterior material proxy (quality/finish signal)
- RES - Roof Covering (matrix_id 3296, addition): Roof type/upgrade proxy
- RES - Heat/AC (matrix_id 1598, addition): Mechanical system proxy
- RES - Fixture Count (matrix_id 3267, addition): Interior finish proxy (counts)

Data: Benton County Dashboard 2024full test.xlsx (Valid Sales), 2024 sales with county ratio code 100. Ratio = assessed value at sale date divided by adjusted sale price. COD co

Exhibit B: Segment proof sheets (Berry test applied to Benton data)

Subset 111 | 2024 valid sales (county ratio code 100) | n=53 | Date range 2024-01-02 to 2024-07-31



Diagnostics (within-subset Berry test)

Median sale price:	$484,900
P10 to P90 price:	$376,800 to $715,000
Median ratio:	0.946
COD:	5.94%
PRD (approx):	1.0089
Controlled tilt beta (ln price):	-0.466 (p=8.4e-10, n=53)

What this shows: The countywide metrics can look neutral, but within this subset we observe statistically significant price-tilt after controlling for size, age, and condition. Negative beta means higher-priced sales have lower ratios within the subset (Berry-style vertical inequity signal).

Benton control levers to address within-segment tilt

- RES - Exterior Wall (matrix_id 3300, addition): Exterior material proxy (quality/finish signal)
- RES - Roof Covering (matrix_id 3296, addition): Roof type/upgrade proxy
- RES - Heat/AC (matrix_id 1598, addition): Mechanical system proxy
- RES - Fixture Count (matrix_id 3267, addition): Interior finish proxy (counts)

Data: Benton County Dashboard 2024full test.xlsx (Valid Sales), 2024 sales with county ratio code 100. Ratio = assessed value at sale date divided by adjusted sale price. COD co

Exhibit B: Segment proof sheets (Berry test applied to Benton data)

Subset 112 | 2024 valid sales (county ratio code 100) | n=184 | Date range 2024-01-02 to 2024-07-29



Diagnostics (within-subset Berry test)

Median sale price:	$494,950
P10 to P90 price:	$392,555 to $686,955
Median ratio:	0.961
COD:	4.22%
PRD (approx):	1.0026
Controlled tilt beta (ln price):	-0.190 (p=6.2e-07, n=183)

What this shows: The countywide metrics can look neutral, but within this subset we observe statistically significant price-tilt after controlling for size, age, and condition. Negative beta means higher-priced sales have lower ratios within the subset (Berry-style vertical inequity signal).

Benton control levers to address within-segment tilt

- RES - Exterior Wall (matrix_id 3300, addition): Exterior material proxy (quality/finish signal)
- RES - Roof Covering (matrix_id 3296, addition): Roof type/upgrade proxy
- RES - Heat/AC (matrix_id 1598, addition): Mechanical system proxy
- RES - Fixture Count (matrix_id 3267, addition): Interior finish proxy (counts)

Data: Benton County Dashboard 2024full test.xlsx (Valid Sales), 2024 sales with county ratio code 100. Ratio = assessed value at sale date divided by adjusted sale price. COD co