

9)

i) Top left: General Tolerances

Top Right: Drawer's Name

Bottom Left: Material Finish

Bottom Middle: Project Number

ii)

The Issues:

- (1) The 8.27 dimension on top right doesn't match with 11 dimension on bottom right.

- (2) The size of the hole on bottom right is given as a radius curve, not a diameter circle.

- (3) The 84.53 dimension on bottom left adds confusion and is not the correct way of measuring that surface.

- (4) The 110.39 dimension on the bottom right, while not being incorrect, should be a different dimension that gives the same information in a more readable way.

- (5) The 35(?) dimension and 98(?) dimension on the top left are overlapping and difficult to read, hence the (?).

To fix them:


- (1) Remove the 8.27 dimension as based on visual cues and comparing with other dimensions it is incorrect and 11 is correct.

- (2) Change the dimension to a diameter (i.e. $\varnothing 38$).

- (3) Remove the dimension as we already have enough information from top left to create that portion of the drawing.

- (4) Remove the dimension and add a dimension to the bottom left of the bottom left drawing for how high the vertical segment should be before the chamfer.

- (5) Move the dimension text to make it more readable.



need another
view to show height
of

