
CRS Shifting Examples

Expected Behavior for Pixel Map Plots

The following example shows what the pixel map plots should look like normally for RMS and mean. You see small square-shaped blank area, which corresponds to the chips we excluded. This is expected and not a cause for concern.

Up to date




Up to date



Up to date



Up to date



Up to date




Up to date



Up to date




Up to date





Missing IO Channel Example

In the following example, you can see a large blank area on the right side of the pixel map plot, where approximately one-fourth of a tile is missing. This is an example where an "IO channel" is missing, and if you see something similar but still with some more pixels in the mostly blank region, it is still a missing IO channel. CRO expert on shift should be contacted immediately to fix it.



Hot Pixel Example

In the following example, you can see one or multiple hot pixels on IOG6T3, causing the data rate for that tile to rise above the 5000p/s yellow line, and 50000p/s red line for a long period of time. If you see a tile with sustained data rate above 5000p/s, send a slack message on 2x2_operations channel tagging the CRO expert on shift. However, this is not as urgent as a missing IO channel and there's no need to make a call to the CRO experts.



Updated by Chuyue Michaelia Fang 1 day ago · 7 revisions