


PSC Functional Test Report







PSC Functional Test Results	
Power Supply Controller Configuration	
Serial Number	0008
Number of Channels	3
Resolution	MS (18bit)
Bandwidth	F
Polarity	Bipolar









Channel 1

ATE Fault Tests for Channel 1	
Fault #1 Generated and Cleared	PASS
Fault #2 Generated and Cleared	PASS
Fault SPARE Generated and Cleared	PASS
Fault DCCT Generated and Cleared	PASS







Power Supply Regulation for Channel 1:







Jump Test Results: CH1






Jump Test Results: CH1






Jump Test Results: CH1





Smooth Test Results: CH1



Smooth Test Results: CH1









Smooth Test Results: CH1









Channel 2

ATE Fault Tests for Channel 2	
Fault #1 Generated and Cleared	PASS
Fault #2 Generated and Cleared	PASS
Fault SPARE Generated and Cleared	PASS
Fault DCCT Generated and Cleared	PASS







Power Supply Regulation for Channel 2:







Jump Test Results: CH2






Jump Test Results: CH2






Jump Test Results: CH2





Smooth Test Results: CH2



Smooth Test Results: CH2









Smooth Test Results: CH2









Channel 3

ATE Fault Tests for Channel 3	
Fault #1 Generated and Cleared	PASS
Fault #2 Generated and Cleared	PASS
Fault SPARE Generated and Cleared	PASS
Fault DCCT Generated and Cleared	PASS







Power Supply Regulation for Channel 3:







Jump Test Results: CH3






Jump Test Results: CH3






Jump Test Results: CH3





Smooth Test Results: CH3



Smooth Test Results: CH3



Smooth Test Results: CH3



FOFB TX test (Bandwidth-Mode = Fast)

PV	Value	Pass?
lab{2}Chan1:DAC-I	0.006438307464122772	FAIL
lab{2}Chan2:DAC-I	0.0	FAIL
lab{2}Chan3:DAC-I	0.006438307464122772	FAIL
lab{2}Chan4:DAC-I	-0.01797795481979847	FAIL

UDP RX Packet Test

(no packets captured)

(Full tcpdump log saved to /home/pstester/MikeDevEnv/ALSU-PSC_CAL-AND-TEST-SUITE/Test_And_Cal_Data/Raw_Logs/Shipment_13/4ch_MSF_SN0008_RawData_01-23-26_15-27/tcpdump_full.log)

Test	Result
UDP RX FOFB	FAIL