


PSC Functional Test Report







PSC Functional Test Results	
Power Supply Controller Configuration	
Serial Number	1035
Number of Channels	4
Resolution	MS (18bit)
Bandwidth	S
Polarity	Unipolar









Channel 1

ATE Fault Tests for Channel 1	
Fault #1 Generated and Cleared	PASS
Fault #2 Generated and Cleared	PASS
Fault SPARE Generated and Cleared	PASS
Fault DCCT Generated and Cleared	PASS







Power Supply Regulation for Channel 1:







Jump Test Results: CH1






Jump Test Results: CH1






Jump Test Results: CH1





Smooth Test Results: CH1



Smooth Test Results: CH1









Smooth Test Results: CH1









Channel 2

ATE Fault Tests for Channel 2	
Fault #1 Generated and Cleared	PASS
Fault #2 Generated and Cleared	PASS
Fault SPARE Generated and Cleared	PASS
Fault DCCT Generated and Cleared	PASS







Power Supply Regulation for Channel 2:







Jump Test Results: CH2






Jump Test Results: CH2






Jump Test Results: CH2





Smooth Test Results: CH2



Smooth Test Results: CH2









Smooth Test Results: CH2









Channel 3

ATE Fault Tests for Channel 3	
Fault #1 Generated and Cleared	PASS
Fault #2 Generated and Cleared	PASS
Fault SPARE Generated and Cleared	PASS
Fault DCCT Generated and Cleared	PASS







Power Supply Regulation for Channel 3:







Jump Test Results: CH3






Jump Test Results: CH3






Jump Test Results: CH3





Smooth Test Results: CH3



Smooth Test Results: CH3









Smooth Test Results: CH3









Channel 4

ATE Fault Tests for Channel 4	
Fault #1 Generated and Cleared	PASS
Fault #2 Generated and Cleared	PASS
Fault SPARE Generated and Cleared	PASS
Fault DCCT Generated and Cleared	PASS







Power Supply Regulation for Channel 4:







Jump Test Results: CH4






Jump Test Results: CH4






Jump Test Results: CH4



Smooth Test Results: CH4



Smooth Test Results: CH4



Smooth Test Results: CH4

