



DETAILS OF CRACK MONITORING

GHG Reference	S2520891
Name of Insured	Mrs H Thomas
Risk Address	Mapletree Cottage, Kings Mead, Pebmarsh, Halstead, CO9 2NA, United Kingdom
Telephone	
Mobile	

All measurements are in mm.

Barclays House, 20-24 Upper Market Street, Eastleigh, Hampshire, SO50 9FD
GHG Solutions Limited, Registered In England, Company Registration No: 3007129
GHG Solutions Limited is authorised and regulated by the Financial Conduct Authority, firm reference number 913965
Registered office, Barclays House 20-24 Upper Market Street, Eastleigh, Hampshire SO50 9FD




LOCATION DETAILS

Location	External RH elevation where outrigger meets main house
Crack Width	25.00
Alignment	Vertical



GRAPH OF CRACK MOVEMENT



MONITORING READINGS

08/11/2025	Notes	Segment	Alignment	Value	+/-Initial	+/-Previous
Initial Reading		A-B	Horizontal	46.140	0.000	0.000
		B-C	Vertical	25.233	0.000	0.000
		A-C	Diagonal	51.903	0.000	0.000
27/01/2026	Notes	Segment	Alignment	Value	+/-Initial	+/-Previous
SML		A-B	Horizontal	35.930	-10.210	-10.210
		B-C	Vertical	26.780	1.547	1.547
		A-C	Diagonal	43.310	-8.593	-8.593
18/03/2026	Notes	Segment	Alignment	Value	+/-Initial	+/-Previous
SML		A-B	Horizontal	30.517	-15.623	-5.413
		B-C	Vertical	26.757	1.523	-0.023
		A-C	Diagonal	38.243	-13.660	-5.067
01/05/2026	Notes	Segment	Alignment	Value	+/-Initial	+/-Previous
SML		A-B	Horizontal	30.417	-15.723	-0.100
		B-C	Vertical	26.600	1.367	-0.157
		A-C	Diagonal	38.123	-13.780	-0.120


17/06/2026	Notes	Segment	Alignment	Value	+/-Initial	+/-Previous
SML		A-B	Horizontal	31.140	-15.000	0.723
		B-C	Vertical	26.720	1.487	0.120
		A-C	Diagonal	37.790	-14.113	-0.333
10/08/2026	Notes	Segment	Alignment	Value	+/-Initial	+/-Previous
SML		A-B	Horizontal	33.950	-12.190	2.810
		B-C	Vertical	26.680	1.447	-0.040
		A-C	Diagonal	40.930	-10.973	3.140

LOCATION DETAILS

Location	External Front Porch Below RHS of window
Crack Width	3.00
Alignment	Vertical



GRAPH OF CRACK MOVEMENT



MONITORING READINGS

08/11/2025	Notes	Segment	Alignment	Value	+/-Initial	+/-Previous
Initial Reading	front	A-B	Horizontal	49.170	0.000	0.000
		B-C	Vertical	34.353	0.000	0.000
		A-C	Diagonal	53.013	0.000	0.000
27/01/2026	Notes	Segment	Alignment	Value	+/-Initial	+/-Previous
SML		A-B	Horizontal	48.853	-0.317	-0.317
		B-C	Vertical	34.590	0.237	0.237

		A-C	Diagonal	52.630	-0.383	-0.383
18/03/2026	Notes	Segment	Alignment	Value	+/-Initial	+/-Previous
	SML	A-B	Horizontal	48.763	-0.407	-0.090
		B-C	Vertical	34.897	0.543	0.307
		A-C	Diagonal	52.510	-0.503	-0.120
01/05/2026	Notes	Segment	Alignment	Value	+/-Initial	+/-Previous
	SML	A-B	Horizontal	48.740	-0.430	-0.023
		B-C	Vertical	34.800	0.447	-0.097
		A-C	Diagonal	52.523	-0.490	0.013
17/06/2026	Notes	Segment	Alignment	Value	+/-Initial	+/-Previous
	SML	A-B	Horizontal	48.970	-0.200	0.230
		B-C	Vertical	34.840	0.487	0.040
		A-C	Diagonal	52.720	-0.293	0.197
10/08/2026	Notes	Segment	Alignment	Value	+/-Initial	+/-Previous
	SML	A-B	Horizontal	48.870	-0.300	-0.100
		B-C	Vertical	34.760	0.407	-0.080
		A-C	Diagonal	52.650	-0.363	-0.070