



DETAILS OF CRACK MONITORING

GHG Reference	S2520891
Name of Insured	Mrs H Thomas
Risk Address	Mapletree Cottage, Kings Mead, Pebmarsh, Halstead, CO9 2NA, United Kingdom
Telephone	
Mobile	

All measurements are in mm.

Barclays House, 20-24 Upper Market Street, Eastleigh, Hampshire, SO50 9FD
GHG Solutions Limited, Registered In England, Company Registration No: 3007129
GHG Solutions Limited is authorised and regulated by the Financial Conduct Authority, firm reference number 913965
Registered office, Barclays House 20-24 Upper Market Street, Eastleigh, Hampshire SO50 9FD




LOCATION DETAILS

Location	Monitoring station - side left
Crack Width	25.00
Alignment	Vertical



GRAPH OF CRACK MOVEMENT



MONITORING READINGS


08/11/2025	Notes	Segment	Alignment	Value	+/-Initial	+/-Previous
Initial Reading		A-B	Horizontal	46.140	0.000	0.000
		B-C	Vertical	25.233	0.000	0.000
		A-C	Diagonal	51.903	0.000	0.000
27/01/2026	Notes	Segment	Alignment	Value	+/-Initial	+/-Previous
SML		A-B	Horizontal	35.930	-10.210	-10.210
		B-C	Vertical	26.780	1.547	1.547
		A-C	Diagonal	43.310	-8.593	-8.593

LOCATION DETAILS

Location	Monitoring Station Front
Crack Width	3.00
Alignment	Vertical



GRAPH OF CRACK MOVEMENT



MONITORING READINGS

08/11/2025	Notes	Segment	Alignment	Value	+/-Initial	+/-Previous
Initial Reading	front	A-B	Horizontal	49.170	0.000	0.000
		B-C	Vertical	34.353	0.000	0.000
		A-C	Diagonal	53.013	0.000	0.000
27/01/2026	Notes	Segment	Alignment	Value	+/-Initial	+/-Previous
SML		A-B	Horizontal	48.853	-0.317	-0.317
		B-C	Vertical	34.590	0.237	0.237
		A-C	Diagonal	52.630	-0.383	-0.383