




Inventory
management
solutions

CHECK-OUT REPORT

Property Address:	
Property Type:	
Date:	[Publish Date]
Instructing Principal:	Microsoft

Property: [Subject]

INVENTORY MANAGEMENT SOLUTIONS

Date: [Publish Date]

Address: [Subject]

Tenant:

Meter Readings:

Electric Reading 05608



Gas Reading 08007



Water Reading N/A

Keys Received at Check In: 2 front door, 2 back door, 1 + 1 outbuilding, 1 deadbolt, 1 unknown yale

Keys Received at Check Out: 2 front door mortice, 2 back door mortice, 1 + 1 outbuilding, 1 deadbolt, 1 unknown yale

Different key returned for 2nd outbuilding, keys returned checked and working

Tenant Forwarding Address:

Tenant E-mail Address:

General Condition

The property is generally well presented/consistent with the inventory. The property has been cleaned with a few omissions. Carpets have been cleaned by the Tenant.

The rear bedroom has been redecorated and receipt provided for re-imbursement.

The bins and recycling boxes are full.

Gardens including hedges have been tended.

The mosaic framed mirror in the bathroom is not located and tenant says never present.

Property: [Subject]

Microsoft

with reference to:

[Subject]

The following are the dilapidations that have occurred at the above property during the tenancy from **03/01/2013** until [Publish Date].

If the tenant can state where items not seen may be found, no charge will be made in respect of those items unless they are damaged.

The inventory used to compile this check out report was created by **Inventory Management Solutions**, dated **09 October 2013**. This report is prepared without prejudice to the accuracy of the inventory at said date.

Items listed represent depreciations, or charges which in our opinion are the liability of either the Landlord or the Tenant. It is acknowledged that the terms of the Tenancy Agreement may overrule recommendations made.

ABBREVIATIONS			
AV	Average (well used/signs of wear/some marks)	NC	No charge
BA	Below average (tired/worn/numerous marks)	NFC	Not freshly cleaned
BOM	Burnt on marks	NOC	Normal outdoor condition
CC	Cleaning charges – tenant cost	NTC	Not thoroughly cleaned
CWA	Consistent with age	NT	Not tested
DLS	Double light switch	NV	No value
DPP	Double power point	NUM	Normal usage marks
EX	Excellent (as new/unmarked/unused)	ODU	Old defects under
FM	Finger marked	P	Poor (very marked/damaged/soiled)
FW	Facing wall	RHS	Right hand side
FWT	Fair wear and tear	RHW	Right hand wall
G	Good (good order with slight wear)	RW	Rear wall
IU	In use	SLS	Simple light switch
IWO	In working order	SPP	Single power point
LHS	Left hand side	T&W	Tested and working
LHW	Left hand wall	VG	Very good (not new but unmarked/in clean condition)
LL	Landlord responsibility	WGP	White gloss painted
MI – LC	Maintenance issue – Landlord cost	WTM	Water marked
MI – TC	Maintenance issue – tenant cost	?	Confirmation required

Property: [Subject]

Item Ref. (as on inv)	Room	Item	Description	Comment	Photo #
3.	Front approach	Refuse	Recycling boxes	All full CC	1
5.	Front approach	Side garden	Laid to concrete and gravel	Weeds and rubbish, as inv MI-LC	
7.	Front approach	Integral outbuilding	Grey handle brush Swing bin	Not located FWT Not located FWT	
8.	Front approach	Side outbuilding	1 blue metal toilet roll holder 2 white metal folding chairs (BA)	Not located? Not located FWT	
12.	Rear garden	Refuse	Green wheelie bin Grey wheelie bin	Bins full CC	1
19.	Hall	Skirting	Cream GP	Dirty as inv LL-CC	
20.	Hall	Flooring	Mottled beige carpet Coir doormat	Cleaned by T, remains greying CC Replaced with ribbed doormat FWT	
28.	Lounge	Skirting	Cream GP	Dirty in places as inv. LL-CC	
34.	Lounge	Furniture	1 mid wood effect veneered drop leaf dining table	Noted as removed following check in	
36.	Lounge	Miscellaneous	1 white metal 4 candle holder 4 glass candle votives on green base	Not located FWT	
50.	Kitchen	Skirting	WGP	NTC CC	
57.	Kitchen	Kitchen units	1 unit with shelf and drawer over	Chip to drawer veneer FWT	
58.	Kitchen	Appliances	Fridge freezer Extractor hood Oven	NTC on top CC Outer casing NTC CC Cleaned, few BOM remain on grill pan and oven bottom, appears better than inv. FWT	2
62.	Kitchen	Miscellaneous	Wooden knife block with 5 knives 1 white metal 4 point candelabra	Not located, possibly removed by accident MI-TC Not located, does not recall?	

Property: [Subject]

Item Ref. (as on inv)	Room	Item	Description	Comment	Photo #
66.	Utility	Walls	Painted cream	LHW door handle dent FWT	
67.	Utility	Wall fixtures	Shelves: 4 vertical brackets, 12 white metal brackets, 3 shelves	6 white metal brackets not located, remainder as described. T does not recall other brackets?	
68.	Utility	Skirting	WGP	Dirty behind door CC	3
71.	Utility	Appliances	Washing machine	Seal stained as inv. LL-CC Drawer powder gunged CC	4
91.	Bedroom 1	Flooring	Brown carpet	Cleaned by T. Long grey line mark in doorway CC	
110.	Landing cupboard	Miscellaneous		Selection of bedding, not on inv. T says not theirs LL-CC?	
111.	Bedroom 2	Door	Cream GP	2 hooks added to reverse FWT	
114.	Bedroom 2	Walls	Paper and painted cream	Redecorated by T. Cream and 1 brown wall, receipt provided for re-imbursement MI-LC	
118.	Bedroom 2	Flooring	Brown carpet	Rough patch/burn mark in doorway, T says existing? Damages TC?	5
130.	Bathroom	Ceiling fixtures	Lighting: rose, bulb, green/white shade	Fitting replaced by electrician	
131.	Bathroom	Walls	Part painted cream, part beige tiled	LHW 2 screws and 2 screw holes in tiles, T says pre-existing?	
133.	Bathroom	Wall ornaments	Mosaic effect framed mirror	Not located, T says never existed? Removed leaving screws/holes as above?	
139.	Bathroom	Bathroom suite	Toilet	NTC around rim CC Seat hinges loose MI-LC	

Photos

1



2



3



4



5

