

XXXXXXXXXXXX

XXXXXXXX: 2026-08-31 16:21:36




XXXXXXXXXXXXXXXXXXXX


XXX	XXX	XXX	XX	XXXXXX
XXXX (Momentary Aerodynamic Thrust [N])	XX=25196.8	XX=5804.47	XX=15007.13	XXXX=306.35 s
XXXX (Momentary Aerodynamic Torque [Nm])	XX=19842.7	XX=-2920.24	XX=7250.51	XXXX=307.75 s
XXXX (Momentary Aerodynamic Power [W])	XX=10397.9	XX=-1530.26	XX=3799.39	XXXX=307.75 s
XXXX [Nm]	XX=119657.21	XX=26881.34	XX=72545.86	--
XXXXXX	Blade_1	XX=16260.66665664998 N	--	--
XXXXXXXXXX	0.026836954708684625	--	--	--

XXXXXXXXXX

XXXX	E35-OUTCQ.txt
XXXXX	213.92 MB
XXXXX	
XXXXX	
XXXXX	31.08.2026 at 15:31:11
XX	12001 X x 1526 X
XXXX	3
XXXX	20
XXXX	20.0 Hz
XX	600.0 s
XXXXX	74XXXX, 3XX, 12XXXX, 60XXXX

XXXXXXXXXXXX





total_rms	total_normal_max	total_normal_min	total_normal_peak_to_peak	total_normal_rms	combined_load_max	combined_load_min
148021	16237.586149275909	-15755.462064657078	31993.048213932987	7803.1586948916765	16260.66665664998	22.40952694463287
8350451	15485.366025094196	-15813.045331252724	31298.411356346922	7756.090640572014	15835.032926477435	12.096100600162465
1050652	15207.41002283608	-15091.806953436371	30299.21697627245	7773.063001136917	15228.924331871309	26.674254952292127



total_normal_del	total_normal_cycles	total_tangential_damage	total_tangential_del	total_tangential_cycles	combined_load_damage	combined_load_cycles
13.79807759875	1545.0	5.431761337620629	1616.8851931873976	1285.0	238.34932157719817	5238.534373700001
96.509355842476	1543.0	5.631466475513031	1633.5019721370566	1292.0	236.36756726931114	5245.151007210001
04.812737090514	1563.0	5.75832613150071	1643.559486246453	1297.0	220.79203371470604	5080.195641280001



max_blade_damage	238.34932157719817
mean_blade_damage	231.8363075204051

damage_imbalance	0.033865605735007326
------------------	----------------------