



(a) Site-level error, both pathways

imagery-free pathway closer at 56 % of sites with street view
and 72 % of sites without



(b) Sites without street view (n = 25)

street-view service MAE 7.7 °C, extreme 5/18
imagery-free pathway MAE 6.2 °C, extreme 9/18



- street view at the site (n = 55)
- ◆ no street view at the site (n = 25); in (b) imagery-free pathway
- △ in (b) street-view service, imagery substituted from 43–110 m away or failed