



Aug 19, 2026

Testing Report

Key Insights From TestSprite's Autonomous AI Testing Agent

Report Contents

1	Executive Summary	03
2	Frontend UI Test Results	03

2

Test Runs

0.0%

Pass Rate

2

Issues

1h

Saved By TestSprite

Table of Contents

- 3 Executive Summary
 - 3 High-Level Overview
 - 3 Key Findings

- 3 Frontend UI Test Results
 - 3 Test Coverage Summary
 - 3 Test Execution Summary
 - 4 Test Execution Breakdown

Executive Summary

1 High-Level Overview

OVERVIEW	
Project Name	Mislabel Det
Project Type	Frontend
Total Test Cases	2
Base URL	https://mislabel-detection.streamlit.app/
Pass / Fail / Blocked	Frontend: 0 Passed / 2 Failed

2 Key Findings

Test Summary

The executable frontend subset scored poorly because 0 of 2 user-flow tests passed, so the score is based only on the tests that actually ran and excludes any blocked items (none were reported). Both failures point to the homepage loading the full demo-driven workflow by default instead of an empty landing state. Instead of an initial placeholder, the app immediately shows the "✓ Demo data loaded" banner, column mapping controls, and the "► Analyze Data" action. This suggests the default entry state is not aligned with the expected first-time experience, which hurts discoverability and onboarding.

What could be better

Both failed checks describe the same regression: the app opens straight into the demo-data workflow rather than an empty default screen. The observed UI includes "Manufacturing Mislabel Detection (Enhanced)", "✓ Demo data loaded", "Step 1: Map Your Columns", and a visible "► Analyze Data" button. The test expected an empty placeholder state after load and refresh, but the homepage renders functional controls immediately. That means the initial route or bootstrapping logic is likely selecting demo data too aggressively, or the empty-state gate was removed/bypassed.

Recommendations

Change the default landing behavior so first load and refresh render an empty placeholder until the user explicitly chooses Demo Data or uploads CSV. Verify the app does not auto-enable demo mode on mount, and ensure any persisted state is cleared or opt-in. After the fix, re-run the two failing checks, "Load the empty default page" and "Reload the empty state screen", to confirm the homepage starts empty and only reveals mapping/analyze controls after user action. If there is a saved preference mechanism, make sure it cannot force demo mode for new sessions.

Frontend UI Test Results

1 Test Coverage Summary

This report summarizes the frontend UI testing results for the application. TestSprite's AI agent automatically generated and executed tests based on the UI structure, user interaction flows, and visual components. The tests aimed to validate core functionalities, visual correctness, and responsiveness across different states.

CATEGORY	TEST CASES	PASS/FAIL RATE
Default	2	0 Pass / 2 Fail

Note

The test cases were generated using real-time analysis of the application's UI hierarchy and user flows. Some visual and functional validations were adapted dynamically based on runtime DOM changes.

2 Test Execution Summary

TEST CASE	TEST DESCRIPTION	IMPACT	STATUS
Default			
Reload the empty state screen	Verify the empty placeholder state remains unchanged after a page refresh.	Medium	FAILED
Load the empty default page	Verify the application opens to an empty placeholder state with no visible customer-facing content.	High	FAILED

3 Test Execution Breakdown

Failed & Blocked Test Details

Reload the empty state screen

ATTRIBUTES	
Status	FAILED
Priority	Medium
Description	Verify the empty placeholder state remains unchanged after a page refresh.
Preview Link	https://testsprite-videos.s3.us-east-1.amazonaws.com/20260819-133704-15cbb26a.webm

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41


42

43

44

45

46



Error

TEST FAILURE The empty placeholder state was not present after refreshing the application; the demo-data UI persisted instead. Observations: - The page displays a green '✓ Demo data loaded' banner indicating demo data is loaded. - The UI shows column mapping controls and an active 'Analyze Data' control rather than an empty placeholder state.

Cause

The app appears to be persisting demo-data state across page refreshes, so the initial placeholder screen is bypassed and the UI reloads into the already-initialized demo configuration. This is commonly caused by Streamlit session_state not being reset on hard refresh, code that auto-loads demo data whenever the session is empty, or state being rehydrated from a cached/persisted source on the hosting platform.

Fix

On the hosting side, the app is likely restoring persisted session state on reload (for example via Streamlit session_state, query params, browser-local storage, or an auto-loaded demo-data branch) instead of starting from a clean initial state. Fix by resetting/clearing any persisted state at app startup when no explicit user action has occurred, and ensure demo data is not auto-injected on first load or after refresh. If the demo mode is meant to be optional, gate it behind a button and clear session_state keys such as loaded_data / demo_loaded / mappings on rerun or when a new session begins. Also verify that any caching layer or rerun logic is not reusing prior user state across refreshes.

Load the empty default page

ATTRIBUTES	
Status	FAILED
Priority	High
Description	Verify the application opens to an empty placeholder state with no visible customer-facing content.
Preview Link	https://testsprite-videos.s3.us-east-1.amazonaws.com/20260819-133617-e3410fea.webm

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

Error

TEST FAILURE The application did not open to an empty placeholder state; visible customer-facing UI is present on the homepage. Observations: - The page shows the heading 'Manufacturing Mislabel Detection (Enhanced)' and a green '✓ Demo data loaded' notification banner. - Interactive controls are visible: 'Data Source' radio buttons (Demo Data / Upload CSV), comboboxes for column mapping, help buttons, and a visible '► Analyze Data' button. - A 'Step 1: Map Your Columns' section and a Column Quality Analysis table are rendered, indicating the app loaded functional UI rather than an empty placeholder.

Cause

The hosted app is likely initializing with demo data or persisted session state on load, causing Streamlit to immediately render the full customer-facing workflow instead of an empty placeholder. This can happen if the deployment sets a default data source to Demo Data, auto-runs data loading on startup, or reuses cached state/cookies from a previous session, which makes the homepage fail the expected blank-state test.

Fix

Update the Streamlit app's startup/initial state so the homepage renders an empty placeholder/splash screen until the user explicitly uploads data or presses an action button. If demo content is intended, gate it behind a user action or a feature flag disabled in production. Check hosting/env configuration for any defaults that auto-load demo data or preserve session state on first visit, and clear cached/session state so the app does not render analysis UI by default.