

Ergonomics Evaluation Report

Posture Analysis

- Neck Flexion: Yellow
- Shoulder Elevation: Yellow
- Elbow Angle: Red
- Wrist Deviation: Red
- Pelvic Tilt: Red

Workstation Analysis

- Monitor: MonitorHeight: Red
- Monitor: ViewingDistance: Green

Pain & Risk Summary

Average Pain Level: 7


Main Pain Region(s): Neck, Elbows/Forearms, Wrists/Hands, Hips/Glutes (VAS 8)

Posture & Ergonomic Corrections

- Reduce wrist deviation to under 10°: Adjust your wrist position so that it remains as straight as possible while typing or using the mouse. Aim for less than 10° deviation to minimize strain and comply with ISO 9241-5.
- Lower elbow angle to 100°: Bring your chair closer to the desk and lower armrests so your elbows are bent at approximately 100°, keeping forearms parallel to the floor as per ISO 9241-5.
- Correct pelvic tilt to under 10°: Sit back fully in your chair with your hips and lower back supported. Adjust seat pan and backrest so your pelvis is upright, reducing tilt to less than 10°.
- Reduce shoulder elevation below 5°: Lower your shoulders by relaxing your arms and adjusting armrests to just below elbow height, keeping shoulders neutral and relaxed.
- Raise monitor by 25 cm: Increase your monitor height by 25 cm so the top of the screen is at or just below eye level, reducing neck flexion and upper back strain in accordance with ISO 9241-5.

Final Advice

Your assessment shows high ergonomic risk, especially for upper back and shoulders. Immediate workstation adjustments and targeted exercises are strongly recommended. If pain persists or worsens, consult a healthcare professional.



Annotated posture analysis from your uploaded photo