

Ergonomics Evaluation Report

Posture Analysis

- Neck Flexion: Yellow
- Shoulder Elevation: Yellow
- Elbow Angle: Red
- Wrist Deviation: Yellow
- Pelvic Tilt: Red

Workstation Analysis

- Monitor: MonitorHeight: Red
- Monitor: ViewingDistance: Green

Pain & Risk Summary

Average Pain Level: 7


Main Pain Region(s): Neck, Elbows/Forearms, Hips/Glutes (VAS 8)

Posture & Ergonomic Corrections

- Reduce elbow angle to 100 degrees: Bring your chair closer and lower armrests so elbows are bent at 100 degrees, reducing strain on forearms and shoulders.
- Correct pelvic tilt to under 10 degrees: Sit back fully in your chair with hips and pelvis upright; use lumbar support to maintain a neutral pelvic tilt below 10 degrees.
- Lower neck flexion to under 5 degrees: Raise your monitor so the top is at eye level, keeping your neck nearly vertical with less than 5 degrees of forward bend.
- Lower monitor by 25 cm: Adjust your monitor height down by 25 cm so the top edge is at or just below eye level, minimizing neck flexion.

Final Advice

Your assessment indicates high ergonomic risk, especially for upper back and lower back. Prioritize workstation adjustments and daily exercises. If symptoms persist or worsen, consult a healthcare professional.



Annotated posture analysis from your uploaded photo