

POSTURA

Ergonomics Evaluation Report

Posture Analysis

- Neck Flexion: Yellow
- Shoulder Elevation: Yellow
- Elbow Angle: Red
- Wrist Deviation: Yellow
- Pelvic Tilt: Red

Workstation Analysis

- Monitor: MonitorHeight: Red
- Monitor: ViewingDistance: Green

Pain & Risk Summary

Average Pain Level: 7


Main Pain Region(s): Neck, Elbows/Forearms, Hips/Glutes (VAS 8)

Posture & Ergonomic Corrections

- Reduce pelvic tilt to under 5°: Sit with hips fully back in the chair and use lumbar support to maintain a neutral pelvis. Avoid slouching forward to decrease pelvic tilt from 20° to under 5°.
- Decrease elbow angle to 100°: Lower chair armrests or raise seat so elbows are bent at 90-100°, reducing current angle from 116° to ISO-compliant range.
- Lower shoulder elevation below 5°: Relax shoulders and adjust armrests or desk height so shoulders are not raised, aiming for less than 5° elevation.
- Reduce wrist deviation to under 5°: Keep wrists straight by aligning keyboard and mouse with forearms, reducing deviation from 13° to under 5°.
- Raise monitor by 25 cm: Elevate your laptop screen or use an external monitor so the top of the screen is at or just below eye level, correcting a 25 cm deficit.

Final Advice

Your upper back pain is severe and your workstation shows multiple high-risk ergonomic violations. Please consult a healthcare provider if pain persists or worsens. When performing any posture exercises or stretches, move slowly and stop immediately if you feel pain or tingling.



Annotated posture analysis from your uploaded photo