

POSTURA

Ergonomics Evaluation Report

Posture Analysis

- Neck Flexion: Yellow
- Shoulder Elevation: Yellow
- Elbow Angle: Red
- Wrist Deviation: Yellow
- Pelvic Tilt: Red

Workstation Analysis

- Monitor: MonitorHeight: Red
- Monitor: ViewingDistance: Green

Pain & Risk Summary

Average Pain Level: 7


Main Pain Region(s): Neck, Elbows/Forearms, Hips/Glutes (VAS 8)

Posture & Ergonomic Corrections

- Reduce elbow angle to 100 degrees: Bring your elbows closer to your body so they are bent at approximately 100 degrees, reducing strain on your upper back and shoulders.
- Decrease pelvic tilt to under 10 degrees: Sit upright with hips and pelvis aligned, using lumbar support if needed, to minimize forward pelvic tilt and lower back strain.
- Lower wrist deviation to under 5 degrees: Keep wrists straight and level with forearms while typing, avoiding any upward or sideways bending.
- Raise monitor by 25 cm: Elevate your laptop screen so the top is at or just below eye level, reducing neck and upper back flexion.

Final Advice

Your upper back pain is severe and posture risks are high. Prioritize workstation changes and equipment upgrades immediately. Take frequent breaks, and if pain persists or worsens, consult a healthcare professional. Safety note: Always perform posture exercises slowly and stop if you feel pain.



Annotated posture analysis from your uploaded photo