

POSTURA

Ergonomics Evaluation Report

Posture Analysis

- Neck Flexion: Red
- Shoulder Elevation: Green
- Elbow Angle: Red
- Wrist Deviation: Yellow
- Pelvic Tilt: Red

Workstation Analysis

- Chair: SeatDepth: Green

Pain & Risk Summary

Average Pain Level: 7


Main Pain Region(s): Neck, Elbows/Forearms, Hips/Glutes (VAS 8)

Posture & Ergonomic Corrections

- Raise monitor by 18 cm: Elevate your monitor so the top edge is at eye level, reducing neck flexion from 65° to under 20° as per ISO 9241-5.
- Bend elbows to 90-100 degrees: Adjust arm position so elbows are bent at 90-100°, not extended at 155°, to reduce upper limb strain and comply with ISO 9241-5.
- Reduce wrist deviation to under 5 degrees: Keep wrists straight and aligned with forearms, minimizing deviation from 12° to below 5° to prevent nerve compression.
- Sit with pelvis upright at 0-10 degrees: Adjust sitting posture to keep pelvis tilt under 10°, avoiding excessive forward tilt (currently 63°) to protect lower back.
- Raise chair seat to 46 cm: Increase chair height so feet remain flat and elbows are at desk height, supporting a neutral elbow angle.
- Move keyboard 10 cm closer: Bring keyboard closer to the edge of the desk to prevent overreaching and reduce elbow extension.

Final Advice

Your reported pain levels and posture risks are severe. Please consult a healthcare professional immediately for assessment of possible nerve involvement (tingling, high pain). Follow ergonomic corrections only after medical clearance. Safety note: Always perform posture changes and exercises gently. Stop immediately if you feel pain, numbness, or increased tingling.



Annotated posture analysis from your uploaded photo