

POSTURA

Ergonomics Evaluation Report

Posture Analysis

- Neck Flexion: Red
- Shoulder Elevation: Green
- Elbow Angle: Yellow
- Wrist Deviation: Green
- Pelvic Tilt: Yellow

Workstation Analysis

Pain & Risk Summary

Average Pain Level: 6


Main Pain Region(s): Neck (VAS 8)

Posture & Ergonomic Corrections

- Reduce Neck Flexion: Sit upright with your head aligned over your shoulders. Avoid bending your neck forward; instead, keep your chin level and your gaze straight ahead.
- Optimize Elbow Angle: Adjust your chair and armrests so your elbows are at a 90-degree angle when typing, keeping your forearms parallel to the floor.
- Correct Pelvic Tilt: Sit with your hips fully back in the chair and use lumbar support to maintain a neutral pelvis. Your thighs should be parallel to the floor.
- Raise Monitor Height: Elevate your monitor so the top edge is at or just below eye level. This will reduce the need to flex your neck forward.
- Adjust Chair Height: Set your chair height so your feet are flat on the floor and your knees are at or just below hip level, helping maintain proper pelvic alignment.

Final Advice

Your assessment indicates significant ergonomic risks, especially for your neck and upper back. Prioritize raising your monitor and improving lumbar support. Perform the recommended exercises regularly and consider equipment upgrades to reduce pain and prevent further strain. If pain persists or worsens, consult a healthcare professional.



Annotated posture analysis from your uploaded photo