

Ergonomics Evaluation Report

Posture Analysis

- Neck Flexion: Green
- Shoulder Elevation: Green
- Elbow Angle: Red
- Wrist Deviation: Red
- Pelvic Tilt: Red

Workstation Analysis


Pain & Risk Summary

Average Pain Level: 8

Main Pain Region(s): Elbows/Forearms, Wrists/Hands, Hips/Glutes (VAS 8)

Final Advice

Your reported pain intensity (neck, upper back, wrists/hands all at 9/10) and symptoms (tingling, stiffness) combined with severe ISO 9241-5 violations indicate a red-flag case. Please seek immediate medical evaluation from a licensed healthcare provider before making ergonomic or exercise changes.



Annotated posture analysis from your uploaded photo