

Ergonomics Evaluation Report

Posture Analysis

- Neck Flexion: Yellow
- Shoulder Elevation: Yellow
- Elbow Angle: Green
- Wrist Deviation: Yellow
- Pelvic Tilt: Red

Workstation Analysis


Pain & Risk Summary

Average Pain Level: 6

Main Pain Region(s): Hips/Glutes (VAS 8)

Final Advice

Your reported pain intensity and duration, combined with severe pelvic tilt and high wrist/neck strain, indicate a red-flag case. Please consult a medical professional or occupational health specialist immediately before making ergonomic adjustments or starting exercises.



Annotated posture analysis from your uploaded photo