

POSTURA

Ergonomics Evaluation Report

Posture Analysis

- Neck Flexion: Red
- Shoulder Elevation: Green
- Elbow Angle: Red
- Wrist Deviation: Yellow
- Pelvic Tilt: Red

Workstation Analysis

- Chair: SeatDepth: Green


Pain & Risk Summary

Average Pain Level: 7

Main Pain Region(s): Neck, Elbows/Forearms, Hips/Glutes (VAS 8)

Final Advice

Your reported pain levels (neck, upper back, wrists/hands: 9/10) and severe ISO violations (neck flexion 65°, elbow angle 155°, pelvic tilt 63°) indicate a high risk of serious musculoskeletal injury. Please seek immediate medical evaluation from a licensed healthcare provider before making workstation or posture changes.



Annotated posture analysis from your uploaded photo