

POSTURA

Ergonomics Evaluation Report

Posture Analysis

- Neck Flexion: Red
- Shoulder Elevation: Green
- Elbow Angle: Red
- Wrist Deviation: Yellow
- Pelvic Tilt: Red

Workstation Analysis

- Chair: SeatDepth: Green

Pain & Risk Summary

Average Pain Level: 7


Main Pain Region(s): Neck, Elbows/Forearms, Hips/Glutes (VAS 8)

Posture & Ergonomic Corrections

- Raise monitor by 18 cm: Elevate your monitor so the top edge is at eye level, reducing neck flexion from 65° to below 20° as per ISO 9241-5.
- Bend elbows to 90 degrees: Adjust arm position so elbows are bent at 90°, not 155°, keeping forearms parallel to the floor to reduce strain.
- Reduce wrist deviation to under 5°: Keep wrists straight while typing and using the mouse, aiming for less than 5° deviation to minimize nerve compression.
- Sit with pelvis upright at 0° tilt: Adjust sitting posture so pelvis is neutral (0° tilt), supporting the lower back and aligning the spine.
- Raise chair seat to 46 cm: Increase chair height so feet are flat on the floor and thighs are parallel, supporting a neutral pelvis and elbow angle.
- Move keyboard 10 cm closer: Position keyboard closer to reduce arm extension and maintain elbows at 90°, decreasing upper back and wrist strain.

Final Advice

Your risk level is RED for posture and workstation. Severe neck, upper back, and wrist pain with high ISO violations require urgent workstation changes and medical review. If symptoms persist or worsen, consult a healthcare professional.



Annotated posture analysis from your uploaded photo