

POSTURA

Ergonomics Evaluation Report

Posture Analysis

- Neck Flexion: Red
- Shoulder Elevation: Green
- Elbow Angle: Red
- Wrist Deviation: Yellow
- Pelvic Tilt: Red

Workstation Analysis

- Chair: SeatDepth: Green

Pain & Risk Summary

Average Pain Level: 7


Main Pain Region(s): Neck, Elbows/Forearms, Hips/Glutes (VAS 8)

Posture & Ergonomic Corrections

- Raise monitor by 18 cm: Elevate your monitor so the top edge is at eye level. This will reduce neck flexion from 65° to the ISO-recommended 0–20° range.
- Bend elbows to 90 degrees: Adjust your chair and desk height so your elbows are bent at 90°, not 155°, with forearms parallel to the floor.
- Reduce wrist deviation to under 5°: Position keyboard and mouse directly in front of you and at the same height as your elbows to minimize wrist angle to less than 5°.
- Tilt pelvis to neutral (0–10°): Sit back fully in your chair with your hips and knees at 90°, using lumbar support to keep pelvic tilt under 10°.
- Add lumbar support cushion (10 cm): Place a 10 cm thick lumbar cushion at your lower back to maintain natural lumbar curve and reduce pelvic tilt.
- Lower desk height by 6 cm: Adjust your desk so the surface is 6 cm lower, allowing elbows to rest at 90° and wrists to remain neutral.

Final Advice

Your pain intensity and posture risks are severe. Please consult a healthcare professional immediately for assessment of neck, upper back, and wrist symptoms, especially with tingling present. Do not delay medical evaluation.



Annotated posture analysis from your uploaded photo