

Ergonomics Evaluation Report

Posture Analysis

- Neck Flexion: Yellow risk (Angle: 14.478839399831822°)
- Shoulder Elevation: Yellow risk (Angle: 9.669742626608373°)
- Elbow Angle: Red risk (Angle: 115.18520049537013°)
- Wrist Deviation: Red risk (Angle: 16.322909810074385°)
- Pelvic Tilt: Red risk (Angle: 18.737877101272208°)

Workstation Analysis

Monitor:

- MonitorHeight: Red (Δ 252.36351799964905)
- ViewingDistance: Green (Δ 485.465802192688)

Risk Summary

No risk summary available.

Pain & Risk Summary

Average Pain Level: VAS 7/10

Main Pain Region(s): Neck, Elbows/Forearms, Wrists/Hands, Lower Back (VAS 8)

Future Risk: Medium – Risk of progression if unaddressed

Exercise Recommendations

condition_type

focus_regions

main_pain_region


average_pain_vas

future_risk

recommended_session

Final Advice

Your workstation setup is causing significant ergonomic risks, especially to your upper back, neck, wrists, and shoulders. Immediate adjustments to monitor height, wrist and elbow posture, and lower back support are recommended. Addressing these issues will help reduce pain and prevent further strain. If pain persists or worsens, consult a healthcare professional.



Annotated posture analysis from your uploaded photo