

Ergonomics Evaluation Report

Posture Analysis

- Neck Flexion: Red risk (Angle: 62.707970539783595°)
- Shoulder Elevation: Green risk (Angle: 3.544778004405989°)
- Elbow Angle: Red risk (Angle: 166.1379592834161°)
- Wrist Deviation: Yellow risk (Angle: 11.798722554392217°)
- Pelvic Tilt: Red risk (Angle: 63.20421721222149°)

Workstation Analysis

Chair:

- SeatDepth: Green (Δ 189.79205322265625)

Risk Summary

No risk summary available.

Pain & Risk Summary

Average Pain Level: VAS 7/10

Main Pain Region(s): Neck, Elbows/Forearms, Lower Back (VAS 8)

Future Risk: Medium – Risk of progression if unaddressed

Exercise Recommendations

condition_type

focus_regions

main_pain_region


average_pain_vas

future_risk

recommended_session

Final Advice

Your current posture and workstation setup are causing significant strain, especially in the neck, upper back, and lower back regions. Immediate ergonomic adjustments and regular exercises are strongly recommended to reduce pain and prevent further injury. If pain persists or worsens, consult a healthcare professional.



Annotated posture analysis from your uploaded photo