

Ergonomics Evaluation Report

Posture Analysis

- Neck Flexion: Red risk (Angle: 33.22979275240333°)
- Shoulder Elevation: Yellow risk (Angle: 10.440627141160313°)
- Elbow Angle: Red risk (Angle: 159.3649626009946°)
- Wrist Deviation: Yellow risk (Angle: 10.357063910333427°)
- Pelvic Tilt: Red risk (Angle: 42.94765933531716°)

Workstation Analysis

Risk Summary

No risk summary available.

Pain & Risk Summary

Average Pain Level: VAS 6/10

Main Pain Region(s): Neck, Elbows/Forearms, Lower Back (VAS 8)

Future Risk: Medium – Risk of progression if unaddressed

Exercise Recommendations

condition_type

focus_regions

main_pain_region


average_pain_vas

future_risk

recommended_session

Final Advice

Your current posture and workstation setup present high risks for neck and lower back strain, especially given your reported discomfort. Prioritize raising your monitor, supporting your lower back, and correcting your elbow angle. Perform the recommended exercises regularly, and consider the suggested equipment for significant ergonomic improvement. If pain worsens or persists, consult a healthcare professional. Safety note: Perform all exercises gently and stop if you experience pain.



Annotated posture analysis from your uploaded photo