

Ergonomics Evaluation Report

Posture Analysis

- Neck Flexion: Yellow risk (Angle: 11.204320399882388°)
- Shoulder Elevation: Yellow risk (Angle: 7.691958707474364°)
- Elbow Angle: Yellow risk (Angle: 114.44937428137791°)
- Wrist Deviation: Red risk (Angle: 20.265996171854976°)
- Pelvic Tilt: Red risk (Angle: 18.95672162568638°)

Workstation Analysis

Monitor:

- MonitorHeight: Red (Δ 253.75814604759216)
- ViewingDistance: Green (Δ 488.43716049194336)

Risk Summary

No risk summary available.

Pain & Risk Summary

Average Pain Level: VAS 6/10

Main Pain Region(s): Neck, Wrists/Hands, Lower Back (VAS 8)

Future Risk: Medium – Risk of progression if unaddressed

Exercise Recommendations

condition_type

focus_regions

main_pain_region


average_pain_vas

future_risk

recommended_session

Final Advice

Your assessment shows high ergonomic risk, especially for your upper back, wrists, and shoulders. Immediate workstation adjustments and posture corrections are strongly recommended. If pain or tingling persists or worsens, consult a healthcare professional.



Annotated posture analysis from your uploaded photo