

Ergonomics Evaluation Report

Posture Analysis

- Neck Flexion: Red risk (Angle: 29.509655757407273°)
- Shoulder Elevation: Yellow risk (Angle: 8.961433376586802°)
- Elbow Angle: Red risk (Angle: 174.20026906067423°)
- Wrist Deviation: Yellow risk (Angle: 10.512255429025771°)
- Pelvic Tilt: Green risk (Angle: 1.646029895372935°)

Workstation Analysis

Monitor:

- MonitorHeight: Green (Δ -17.65237522125244)
- ViewingDistance: Green (Δ -448.12235260009766)

Risk Summary

No risk summary available.

Pain & Risk Summary

Average Pain Level: VAS 6/10

Main Pain Region(s): Neck, Elbows/Forearms (VAS 8)

Future Risk: Medium – Risk of progression if unaddressed

Exercise Recommendations

condition_type

focus_regions

main_pain_region


average_pain_vas

future_risk

recommended_session

Final Advice

Your assessment shows significant ergonomic risks, especially for your upper back, neck, and shoulders, with high pain intensity in the upper back. Immediate workstation and posture adjustments are recommended. If pain persists or worsens, consult a healthcare professional.



Annotated posture analysis from your uploaded photo