

Ergonomics Evaluation Report

Posture Analysis

- Neck Flexion: Yellow
- Shoulder Elevation: Yellow
- Elbow Angle: Red
- Wrist Deviation: Yellow
- Pelvic Tilt: Red

Workstation Analysis

- Monitor: MonitorHeight: Red
- Monitor: ViewingDistance: Green

Pain & Risk Summary

Average Pain Level: 7


Main Pain Region(s): Neck, Elbows/Forearms, Hips/Glutes (VAS 8)

Posture & Ergonomic Corrections

- Your elbows are extended at 116°, exceeding the ISO 9241-5 recommended 90–100°. Bring your elbows closer to your body and aim for a more open but relaxed 90–100° angle to reduce upper back and wrist strain.
- You have a forward pelvic tilt of 20°, which is above the ISO 9241-5 limit. Sit back fully in your chair with your hips and lower back supported to maintain a neutral pelvis and reduce upper back discomfort.
- Shoulder elevation is 9.6°, above the ISO guideline of relaxed shoulders. Drop your shoulders and avoid hunching to minimize upper back and neck tension.
- Your wrists are deviated by 12°, which can increase strain. Keep wrists straight and in line with your forearms while typing to reduce risk of tingling and pain.
- Your monitor is 25 cm too low, causing neck flexion and upper back strain. Raise the monitor so the top of the screen is at or just below eye level, per ISO 9241-5.

Final Advice

Your upper back pain is severe and your workstation setup is causing significant ergonomic risks. Prioritize monitor height, lumbar support, and a neutral typing posture. If pain persists or worsens, consult a healthcare professional.



Annotated posture analysis from your uploaded photo