

Ergonomics Evaluation Report

Posture Analysis

- Neck Flexion: Yellow
- Shoulder Elevation: Yellow
- Elbow Angle: Red
- Wrist Deviation: Yellow
- Pelvic Tilt: Red

Workstation Analysis

- Monitor: MonitorHeight: Red
- Monitor: ViewingDistance: Green

Pain & Risk Summary

Average Pain Level: 7


Main Pain Region(s): Neck, Elbows/Forearms, Hips/Glutes (VAS 8)

Posture & Ergonomic Corrections

- Bring your elbows closer to a 90° angle by adjusting your chair height or moving your keyboard closer. This will reduce strain on your forearms and shoulders, as ISO 9241-5 recommends elbow angles between 90° and 110°.
- Sit back fully in your chair with your pelvis neutral (not tilted forward or backward). Use lumbar support to help maintain a neutral pelvic position, as ISO 9241-5 specifies minimal pelvic tilt to prevent lower back strain.
- Relax your shoulders and avoid shrugging. Adjust your armrests or desk height so your shoulders are not elevated, as ISO 9241-5 requires shoulders to remain relaxed and level.
- Raise your monitor by approximately 10 cm so the top of the screen is at or just below eye level. This adjustment aligns with ISO 9241-5, which aims to minimize neck flexion and reduce neck and upper back strain.
- Move your keyboard 5 cm closer to your body to allow your elbows to rest at a more neutral angle and reduce shoulder elevation, as recommended by ISO 9241-5.

Final Advice

Your assessment shows high ergonomic risk, especially for your upper back, shoulders, and lower back, with significant pain reported. Please implement the corrections and exercises above, and consider consulting a healthcare professional if pain persists or worsens.



Annotated posture analysis from your uploaded photo