

POSTURA

Ergonomics Evaluation Report

Posture Analysis

- Neck Flexion: Red
- Shoulder Elevation: Yellow
- Elbow Angle: Red
- Wrist Deviation: Yellow
- Pelvic Tilt: Red

Workstation Analysis

Pain & Risk Summary

Average Pain Level: 7


Main Pain Region(s): Neck, Elbows/Forearms, Hips/Glutes (VAS 8)

Posture & Ergonomic Corrections

- Raise monitor by 15 cm: Elevate your monitor so the top edge is at or just below eye level. This will reduce neck flexion from 43° to the ISO 9241-5 recommended range of 0–20°, decreasing neck and upper back strain.
- Lower chair seat to 44 cm: Adjust your chair so your feet are flat on the floor and thighs are parallel, supporting a neutral pelvic tilt and reducing lower back and upper back discomfort.
- Relax shoulders to neutral position: Consciously drop your shoulders and avoid hunching. Keep them relaxed and level to decrease elevation from 13° to within the ISO recommended 0–10° range, reducing shoulder and upper back tension.
- Bend elbows to 100° angle: Adjust your chair and keyboard height so your elbows are bent at approximately 100°, not exceeding 120°, to comply with ISO 9241-5 and reduce upper limb fatigue.
- Move keyboard 8 cm closer: Position your keyboard so your elbows remain close to your body and wrists are straight, minimizing reach and reducing elbow angle to the ISO recommended 90–110° range.

Final Advice

Your assessment shows severe ergonomic risks, especially for your upper back and shoulders, with high pain intensity and significant ISO 9241-5 violations. Prioritize workstation adjustments and posture corrections immediately. If pain persists or worsens, consult a healthcare professional.



Annotated posture analysis from your uploaded photo