

POSTURA

Ergonomics Evaluation Report

Posture Analysis

- Neck Flexion: Yellow
- Shoulder Elevation: Yellow
- Elbow Angle: Red
- Wrist Deviation: Yellow
- Pelvic Tilt: Red

Workstation Analysis

- Monitor: MonitorHeight: Red
- Monitor: ViewingDistance: Green

Pain & Risk Summary

Average Pain Level: 7


Main Pain Region(s): Neck, Elbows/Forearms, Hips/Glutes (VAS 8)

Posture & Ergonomic Corrections

- Reduce elbow angle to 100°: Bring your elbows closer to your body so they are bent at approximately 100°, which reduces strain on the forearms and shoulders. This aligns with ISO 9241-5 recommendations for neutral elbow posture.
- Decrease pelvic tilt to under 10°: Sit with your pelvis in a more upright position, aiming for less than 10° tilt. Use a lumbar support or adjust your chair backrest to maintain a neutral spine, reducing upper back and lower back strain.
- Lower shoulder elevation below 5°: Relax your shoulders and adjust armrests or desk height so your shoulders are not raised. This helps prevent muscle fatigue and aligns with ISO 9241-5 for relaxed shoulder posture.
- Raise monitor by 25 cm: Increase your monitor height by 25 cm so the top of the screen is at or just below eye level. This will reduce neck flexion and upper back strain, as required by ISO 9241-5.
- Adjust chair height to 46 cm: Set your chair seat height to 46 cm to ensure your feet are flat on the floor and thighs are parallel, supporting a neutral pelvis and reducing upper back discomfort.

Final Advice

Your assessment shows high ergonomic risk, especially for upper back and neck. Prioritize monitor height and lumbar support. If pain persists or worsens, consult a healthcare professional.



Annotated posture analysis from your uploaded photo