

Ergonomics Evaluation Report

Posture Analysis

- Neck Flexion: Yellow
- Shoulder Elevation: Yellow
- Elbow Angle: Red
- Wrist Deviation: Yellow
- Pelvic Tilt: Red

Workstation Analysis

- Monitor: MonitorHeight: Red
- Monitor: ViewingDistance: Green

Pain & Risk Summary

Average Pain Level: 7


Main Pain Region(s): Neck, Elbows/Forearms, Hips/Glutes (VAS 8)

Posture & Ergonomic Corrections

- Reduce elbow angle to 100°: Bring your elbows closer to your body so that the angle between your upper arm and forearm is approximately 100°, reducing strain on your shoulders and upper back.
- Decrease pelvic tilt to under 10°: Sit with your pelvis in a more neutral position by adjusting your chair and consciously tilting your pelvis forward, aiming for less than 10° tilt to support your lower back.
- Lower shoulder elevation to 0°: Relax your shoulders so they are not raised; keep them level and avoid hunching to minimize upper back and shoulder tension.
- Raise monitor by 25 cm: Increase your monitor height by 25 cm so the top of the screen is at or just below eye level, reducing neck flexion and upper back strain.

Final Advice

Your assessment shows high ergonomic risk, especially for upper back and shoulders. Address workstation setup urgently and follow posture corrections. If pain persists or worsens, consult a healthcare professional.



Annotated posture analysis from your uploaded photo