CLOUDFRONT STATIC WEBSITE

PROJECT PROGRESS REPORT

Implementation status captured from the screenshots supplied on 02 October 2026. This is an in-progress report: the distribution was still deploying in the latest evidence, so end-to-end delivery has not yet been verified.

Current stage
S3 website content uploaded; CloudFront distribution created; final deployment and functional checks remain.

Project objective

Publish a static website stored in Amazon S3 through an Amazon CloudFront distribution, then validate the delivered site and document the configuration. The screenshots show AWS region us-east-1 (US East, N. Virginia), an S3 bucket configured for static website hosting, and a CloudFront distribution named **cg-cf**.

Prepared as a progress report. Author name and course details can be added before final submission.

1. Executive summary

The project has reached the distribution setup stage. An S3 bucket was created, static website hosting was enabled, site files were uploaded under a nested folder, and a CloudFront distribution was created with the S3 website endpoint as its origin. The latest screenshot shows the distribution status as **Deploying**. No screenshot in the archive demonstrates a successful CloudFront page load or a completed error-resolution check.

2. Architecture and configuration observed

VISITOR	HTTPS request	**CLOUDFRONT EDGE**	Origin request	**S3 WEBSITE ORIGIN**
Browser	**->**	Distribution: cg-cf Domain shown: d3jyprvy7kpxt4.cloudfront.net	**->**	S3 website endpoint Region: us-east-1

Observed configuration

Area	What the screenshots show
S3 bucket	Created in us-east-1. Versioning is enabled. Static website hosting is enabled and an HTTP website endpoint is displayed.
Website content	A top-level folder named **2167_orbital/** contains another folder with the same name. The inner folder contains images/, index.html, timer.html, a JavaScript file, and a CSS file.
CloudFront	Distribution name cg-cf. One origin is listed as **S3 static website**, with origin path **/2167_orbital**. Default cache settings were shown at creation.
Status and plan	Distribution status was Deploying in the last screenshot. The console showed the Free plan and a $0/month label at the captured time. Actual billing depends on usage and current account terms.

The distribution domain is transcribed from the console screenshot. It is not presented as a tested website URL because the screenshot does not show a successful page load.

3. Findings to address before calling this complete

Priority	Finding from evidence	Next check / action
High	The bucket policy shown grants **s3:GetObject** to Principal *****. The static website endpoint and a public-read policy indicate the origin is publicly readable.	For a private S3 origin, use the S3 REST bucket endpoint with CloudFront Origin Access Control (OAC), then limit the bucket policy to that distribution and keep S3 Block Public Access enabled. If keeping the website endpoint for this exercise, state clearly that the origin is public and avoid storing private content there.
High	The site files appear under **/2167_orbital/2167_orbital/**, while the CloudFront origin path is shown as **/2167_orbital**. That suggests a possible path mismatch.	Confirm the exact S3 key for index.html. Set the origin path to match the directory containing index.html, or move the site files one level up. Then set/check the default root object to index.html and test the CloudFront domain.
Medium	The last CloudFront screenshot shows **Deploying**; cache behavior and successful content delivery are not evidenced.	Wait for status Deployed. Open the distribution domain and verify the home page, image/CSS/JS assets, and a nested URL. Capture the browser result and relevant response/status evidence.
Medium	The S3 website endpoint uses HTTP. CloudFront viewer HTTPS and CloudFront-to-origin encryption settings are not established by these screenshots.	Verify the viewer protocol policy redirects HTTP to HTTPS. Note that S3 website endpoints do not support HTTPS from CloudFront to the origin; the private S3 REST origin plus OAC path is the stronger final architecture.

Public sharing note: The submitted console screenshots visibly include an AWS account number and account identity. Appendix A contains redacted copies; the original screenshots are not embedded. Before uploading any new console screenshots to a public GitHub repository or posting them on LinkedIn, redact account-specific identifiers.

4. Work completed and evidence log

The following steps are supported by the uploaded screenshots. Timestamps are the screenshot filename times on 02 October 2026.

Screenshot time	Evidence captured
19:55:59	S3 bucket policy saved with public GetObject permission for objects.
19:57:34	S3 bucket details in us-east-1; versioning enabled.
19:58:28	Static website hosting enabled; website endpoint displayed.
20:11:49	Bucket Object Ownership set to bucket-owner-enforced; ACL view shows no public ACL grant.
20:13:38-20:14:38	Site files are present in nested 2167_orbital folders; inner folder properties show the nested S3 path.
22:04:36	CloudFront create flow reviewed. Origin is the S3 website endpoint; default cache settings selected.
22:28:02	CloudFront distribution exists and is Deploying. Origin tab shows S3 static website and origin path /2167_orbital.

5. Next steps for the final report

• Confirm whether the S3 folder nesting is intentional and correct the origin path so CloudFront reaches index.html.

• Choose and document the final origin security model. For a private S3 origin, switch from the S3 website endpoint to the bucket REST endpoint and configure OAC.

• Wait for CloudFront to show Deployed, then test the CloudFront URL over HTTPS and verify page assets and direct-origin behavior.

• Record the exact final cache behavior, default root object, viewer protocol policy, and distribution status.

• Capture sanitized screenshots and add the final test results, limitations, and cost note before publishing the PDF.

References

AWS CloudFront: Get started

AWS CloudFront: Origin settings

AWS CloudFront: Restrict access to an S3 origin

AWS S3: Website access permissions

Scope note: This report describes only what can be established from the nine screenshots in cf.zip. Error dialogs, completed distribution deployment, website test results, and a complete validation run were not included in the evidence.

Appendix A. Redacted screenshot evidence

The following screenshots are the supplied evidence with account identity and resource identifiers covered. They document the project state, but do not prove a successful public CloudFront page load.

A1. S3 bucket configuration




Figure A1. S3 bucket overview: US East (N. Virginia) and versioning enabled.




Figure A2. Static website hosting enabled and website endpoint displayed.

Appendix A. Redacted screenshot evidence

A2. Bucket permissions




Figure A3. Bucket policy was saved with public GetObject access. The resource identifier is redacted.




Figure A4. Object Ownership and access control list view.

Appendix A. Redacted screenshot evidence

A3. Website files in Amazon S3




Figure A5. Top-level folder that holds the website content.




Figure A6. Inner folder contains HTML, CSS, JavaScript, and image assets.




Figure A7. Folder details showing the nested S3 path, with identifiers redacted.

Appendix A. Redacted screenshot evidence

A4. CloudFront distribution creation




Figure A8. CloudFront review and create screen. The S3 website origin identifier is redacted.

Appendix A. Redacted screenshot evidence

A5. CloudFront origin after creation




Figure A9. Distribution origin tab: S3 static website origin with origin path /2167_orbital. The distribution was still deploying.