




EL image report



UNIVERSITY of
TASMANIA

Predicted Power Degradation: 0.936






EL image report



UNIVERSITY of
TASMANIA

Predicted Power Degradation: 0.936






EL image report



Predicted Power Degradation: 0.936

Good Classification



 Small Fault Medium Fault Severe Fault




EL image report



UNIVERSITY of
TASMANIA

Predicted Power Degradation: 0.936

Crack Classification



[Legend] Small Crack Medium Crack Severe Crack




EL image report



UNIVERSITY of
TASMANIA

Predicted Power Degradation: 0.936

Corrosion Classification



Small Corrosion Medium Corrosion Severe Corrosion