Background:

T2 = Fabric Supplier: Yu Yuang

Fabric Article#: KP04570JA0

Material composition: 74% Nylon, 26% Lycra

Structure: Double Knit

Color: Dark Jade

Phenomenon:

Easy causing crease marks as below photo showed:



Technical analysis:


Nylon 66 is a thermoplastic with low moisture regain. Under pressure, even room temperature pressure such as hang tag stacking over the time, fibers can take a temporary set which is a visible pressure marks, called “Crease Marks” or “Folding Marks” partially.


尼龍 66 為熱塑性, 低含水率, 在壓力與局部熱作用下易留下表面微結構變化, 俗稱 “壓痕” or 局部 “摺線痕”.

26% Lycra = High content of Spandex, means the fabric is very elastic, if not properly heat-set, the fabric will store mechanical strain and show creases after packing, tagging, or light pressing.


26% Lycra = 高含量氨綸, 易使布面呈高彈性, 若布面的熱定形不足, 面料還殘留機械應力, 受壓力後更容易出現折痕.

Golden Sample reviewed – As we can see from below two photos of golden sample - there are also many crease marks and folding marks on the golden sample:






Below photos under fabric mirror and microscope:







Suggestion:

If steaming could remove the crease marks and folding marks and do not reappear, then these marks should be considered as acceptable.