

Line:

Track class: 80 - 120 km/h

Begin of working: 16/05/2026 15:31:11

Comment:

Machine type:


Filename: MFI57123,16,05,2026.drp

Track:

Maintenance

Working end: 16/05/2026 15:45:48

Machine number:



## Report: Tolerance exceeding

Line, Track: ,  
 Km: -21.500 - 64.000  
 Track class: 80 - 120 km/h

Work: Maintenance  
 Date: 16/05/2026  
 Filename: MFI57123,16,05,2026.drp

| km       | Alignm.D1 | Cant diff. | Twist      | Level D1 |
|----------|-----------|------------|------------|----------|
|          | ±4.0 mm   | ±4.0 mm    | ±1.5 mm/1m | ±4.0 mm  |
| -0,000.5 |           |            | 1-1.7      |          |
| 0,018.0  |           |            | 2+2.0      |          |
| 0,023.5  |           |            | 2-1.9      |          |
| 0,039.5  |           |            | 1+1.5      |          |

## Report: Standard deviation

Line, Track: ,  
Km: -21.500 - 64.000  
Track class: 80 - 120 km/h

Work: Maintenance  
Date: 16/05/2026  
Filename: MFI57123,16,05,2026.drp

| Section | Cant | Alignment | Long. level |
|---------|------|-----------|-------------|
| 64      | 2.23 |           |             |
| Km:     | 2.23 | 0.00      | 0.00        |