

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS
10009019074
Claim #: 070269410955
Policy #:



Personal Property - 24-UPP hail damage

Date Taken: 6/5/2025



Personal Property - 25-UPP hail damage

Date Taken: 6/5/2025

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS
Claim #: 10009019074
Policy #: 070269410955



Personal Property - 37-UPP hail damage

Date Taken: 6/5/2025



Personal Property - 38-UPP hail damage

Date Taken: 6/5/2025

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS

10009019074

Claim #:

070269410955

Policy #:



Dwelling/Exterior - 1-Front view
of risk- no damage

Date Taken: 6/5/2025



Dwelling/Exterior - 2-address

Date Taken: 6/5/2025

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS

10009019074

Claim #:

070269410955

Policy #:



Dwelling/Exterior - 3-Front elevation

Date Taken: 6/5/2025

No peril related damage



Dwelling/Exterior - 4-Front elevation

Date Taken: 6/5/2025

No peril related damage

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS

10009019074

Claim #:

070269410955

Policy #:



Dwelling/Exterior - 5-Front elevation

Date Taken: 6/5/2025

No peril related damage




Dwelling/Exterior - 6-Front elevation

Date Taken: 6/5/2025

No peril related damage

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS
10009019074
Claim #: 070269410955
Policy #:



Dwelling/Exterior - 7-Front elevation

Date Taken: 6/5/2025

No peril related damage



Dwelling/Exterior - 8-Right elevation

Date Taken: 6/5/2025

No peril related damage

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS
10009019074
Claim #: 070269410955
Policy #:



Dwelling/Exterior - 10-Right elevation

Date Taken: 6/5/2025

No peril related damage



Dwelling/Exterior - 11-Right elevation

Date Taken: 6/5/2025

No peril related damage

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS

10009019074

Claim #:

070269410955

Policy #:



Dwelling/Exterior - 12-Right elevation

Date Taken: 6/5/2025

No peril related damage



Dwelling/Exterior - 17-Right Elevation

Date Taken: 6/5/2025

No peril related damage

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS
10009019074
Claim #: 070269410955
Policy #:



Dwelling/Exterior - 23-Back elevation

Date Taken: 6/5/2025

No peril related damage



Dwelling/Exterior - 26-Back elevation

Date Taken: 6/5/2025

No peril related damage

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS
Claim #: 10009019074
Policy #: 070269410955



Dwelling/Exterior - 27-Back elevation

Date Taken: 6/5/2025

No peril related damage



Dwelling/Exterior - 28-Back elevation

Date Taken: 6/5/2025

No peril related damage

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS
10009019074
Claim #: 070269410955
Policy #:



Dwelling/Exterior - 29-Back elevation

Date Taken: 6/5/2025

No peril related damage



Dwelling/Exterior - 30-Back elevation

Date Taken: 6/5/2025

No peril related damage

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS

10009019074

Claim #:

070269410955

Policy #:



Dwelling/Exterior - 31-Back elevation

Date Taken: 6/5/2025

No peril related damage



Dwelling/Exterior - 32-Back elevation

Date Taken: 6/5/2025

No peril related damage


Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS
10009019074
Claim #: 070269410955
Policy #:



Dwelling/Exterior/Roofing -
EastImage.JPG

Date Taken:
Taken By: EagleView



Dwelling/Exterior/Roofing -
NorthImage.JPG

Date Taken:
Taken By: EagleView

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS

10009019074

Claim #:

070269410955


Policy #:



Dwelling/Exterior/Roofing -
SouthImage.JPG

Date Taken:

Taken By: EagleView




Dwelling/Exterior/Roofing -
TopImage.JPG

Date Taken:

Taken By: EagleView

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS
10009019074
Claim #: 070269410955
Policy #:



Dwelling/Exterior/Roofing -
WestImage.JPG

Date Taken:
Taken By: EagleView



Dwelling/Exterior/Roofing/Dwellin
g roof - 39-1
layer/IWS/drip/starter

Date Taken: 6/5/2025

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS
10009019074
Claim #: 070269410955
Policy #:



Dwelling/Exterior/Roofing/Dwelling roof - 40-rake starter

Date Taken: 6/5/2025



Dwelling/Exterior/Roofing/Dwelling roof - 41-pitch

Date Taken: 6/5/2025

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS

10009019074

Claim #:

070269410955

Policy #:



Dwelling/Exterior/Roofing/Dwelling roof - 42-pitch

Date Taken: 6/5/2025



Dwelling/Exterior/Roofing/Dwelling roof - 43-Overview

Date Taken: 6/5/2025

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS
10009019074
Claim #: 070269410955
Policy #:



Dwelling/Exterior/Roofing/Dwelling roof - 44-Overview

Date Taken: 6/5/2025



Dwelling/Exterior/Roofing/Dwelling roof - 45-Overview

Date Taken: 6/5/2025

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS
10009019074
Claim #: 070269410955
Policy #:



Dwelling/Exterior/Roofing/Dwelling roof - 46-Overview

Date Taken: 6/5/2025



Dwelling/Exterior/Roofing/Dwelling roof - 47-Overview

Date Taken: 6/5/2025

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS
Claim #: 10009019074
Policy #: 070269410955



Dwelling/Exterior/Roofing/Dwelling roof - 48-Overview

Date Taken: 6/5/2025



Dwelling/Exterior/Roofing/Dwelling roof - 49-Front slope

Date Taken: 6/5/2025

Test square

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS

10009019074

Claim #:

070269410955

Policy #:



Dwelling/Exterior/Roofing/Dwelling roof - 50-Front slope

Date Taken: 6/5/2025

25% test square



Dwelling/Exterior/Roofing/Dwelling roof - 51-Front slope

Date Taken: 6/5/2025

Hail = 8+ strikes

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS
Claim #: 10009019074
Policy #: 070269410955



Dwelling/Exterior/Roofing/Dwelling roof - 52-Front slope

Date Taken: 6/5/2025

Hail = 8+ strikes



Dwelling/Exterior/Roofing/Dwelling roof - 53-Front slope

Date Taken: 6/5/2025

Hail = 8+ strikes

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS

10009019074

Claim #:

070269410955

Policy #:



Dwelling/Exterior/Roofing/Dwelling roof - 54-Front slope

Date Taken: 6/5/2025

Hail = 8+ strikes



Dwelling/Exterior/Roofing/Dwelling roof - 55-Front slope

Date Taken: 6/5/2025

Hail = 8+ strikes

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS
10009019074
Claim #: 070269410955
Policy #:



Dwelling/Exterior/Roofing/Dwelling roof - 56-Left slope

Date Taken: 6/5/2025



Dwelling/Exterior/Roofing/Dwelling roof - 57-Left slope

Date Taken: 6/5/2025

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS
10009019074
Claim #: 070269410955
Policy #:



Dwelling/Exterior/Roofing/Dwelling roof - 58-Left slope

Date Taken: 6/5/2025

Test square



Dwelling/Exterior/Roofing/Dwelling roof - 59-Left slope

Date Taken: 6/5/2025

25% test square

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS
Claim #: 10009019074
Policy #: 070269410955



Dwelling/Exterior/Roofing/Dwelling roof - 60-Left slope

Date Taken: 6/5/2025

Hail = 8+ strikes



Dwelling/Exterior/Roofing/Dwelling roof - 61-Left slope

Date Taken: 6/5/2025

Hail = 8+ strikes

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS
Claim #: 10009019074
Policy #: 070269410955



Dwelling/Exterior/Roofing/Dwelling roof - 62-Left slope

Date Taken: 6/5/2025

Hail = 8+ stirkes



Dwelling/Exterior/Roofing/Dwelling roof - 63-Left slope

Date Taken: 6/5/2025

Hail = 8+ stirkes

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS

10009019074

Claim #:

070269410955

Policy #:



Dwelling/Exterior/Roofing/Dwelling roof - 65-Back slope

Date Taken: 6/5/2025



Dwelling/Exterior/Roofing/Dwelling roof - 66-Back slope

Date Taken: 6/5/2025

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS

10009019074

Claim #:

070269410955

Policy #:



Dwelling/Exterior/Roofing/Dwelling roof - 67-Back slope

Date Taken: 6/5/2025

Test square



Dwelling/Exterior/Roofing/Dwelling roof - 68-Back slope

Date Taken: 6/5/2025

25% test square

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS

10009019074

Claim #:

070269410955

Policy #:



Dwelling/Exterior/Roofing/Dwelling roof - 69-Back slope

Date Taken: 6/5/2025

Hail = 8+ stirkes



Dwelling/Exterior/Roofing/Dwelling roof - 70-Back slope

Date Taken: 6/5/2025

Hail = 8+ stirkes

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS
Claim #: 10009019074
Policy #: 070269410955



Dwelling/Exterior/Roofing/Dwelling roof - 71-Back slope

Date Taken: 6/5/2025

Hail = 8+ strikes



Dwelling/Exterior/Roofing/Dwelling roof - 72-Back slope

Date Taken: 6/5/2025

Hail = 8+ strikes


Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS
10009019074
Claim #: 070269410955
Policy #:



Dwelling/Exterior/Roofing/Dwelling roof - 73-Right slope

Date Taken: 6/5/2025



Dwelling/Exterior/Roofing/Dwelling roof - 64-ridge hail

Date Taken: 6/5/2025

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS

10009019074

Claim #:

070269410955

Policy #:



Dwelling/Exterior/Deck - 33-
Deck rail paint damage hail

Date Taken: 6/5/2025



Dwelling/Exterior/Deck - 34-
Deck rail paint damage hail

Date Taken: 6/5/2025

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS

10009019074

Claim #:

070269410955

Policy #:



Dwelling/Exterior/Deck - 35-
Deck rail paint damage hail

Date Taken: 6/5/2025



Dwelling/Exterior/Deck - 36-
Deck rail paint damage hail

Date Taken: 6/5/2025

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS

10009019074

Claim #:

070269410955

Policy #:



Unscheduled Other Structures/Fencing - 9-Right elevation

Date Taken: 6/5/2025

No peril related damage



Unscheduled Other Structures/Fencing - 13-Left fence

Date Taken: 6/5/2025

No peril related damage

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS

10009019074

Claim #:

070269410955

Policy #:



Unscheduled Other Structures/Fencing - 14-Left fence

Date Taken: 6/5/2025

No peril related damage



Unscheduled Other Structures/Fencing - 15-No damage - splatter only

Date Taken: 6/5/2025

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS

10009019074

Claim #:

070269410955

Policy #:



Unscheduled Other Structures/Fencing - 16-No damage - splatter only

Date Taken: 6/5/2025



Unscheduled Other Structures/Fencing - 18-No damage - splatter only

Date Taken: 6/5/2025

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS

10009019074

Claim #:

070269410955

Policy #:



Unscheduled Other Structures/Fencing - 19-No damage - splatter only

Date Taken: 6/5/2025



Unscheduled Other Structures/Fencing - 20-No damage - splatter only

Date Taken: 6/5/2025

Photo Sheet

Insured: BRAD GILTAS AND KHRIS GILTAS

10009019074

Claim #:


070269410955

Policy #:



Unscheduled Other Structures/Fencing - 21-No damage - splatter only

Date Taken: 6/5/2025



Unscheduled Other Structures/Fencing - 22-No damage - splatter only

Date Taken: 6/5/2025