



Republic of the Philippines
City of Cagayan de Oro
**CITY DISASTER RISK REDUCTION AND
MANAGEMENT DEPARTMENT
ORO RESCUE 911**

Republic of the Philippines
City of Cagayan de Oro
OFFICE OF THE CITY ENGINEER
26 AUG 2026 9:53 AM
RECEIVED
Shella Jan R. Pata, City Engineer
Administrative Officer
City of golden friendship
Date: ARNOLD S. DE SAN MIGUEL
City Council Secretary
REMARKS

For : Hon. Enrico D. Salcedo
Chairperson of the Committee on Environment
City Councilor, Cagayan de Oro City

From : City Disaster Risk Reduction and
Management Department (CDRRMD)

Re : Survey and Site Assessment of Reported Riverbank Erosion along Purok 3, Brgy.
Gusa, Cagayan de Oro City

Date August 25, 2026

I. GENERAL INFORMATION

A. Date: August 05, 2026

B. Location: Sekyup Ilaya, Purok 3, Barangay Gusa, Cagayan de Oro City

C. Participants: City Disaster Risk Reduction and Management Department, City Engineering Office, CLENRO, DPWH 10 – 1st District Engineering Office, Barangay Gusa Council, in connection with the request of Mr. Reynante Namocatcat.

D. CDRRMD – Oro Rescue 911 Personnel Deployed:

Mr. Jerold Bon Lago
Mr. Jan Helton Ecot
Mr. John Navarro

II. NARRATIVE

The landowner raised concerns regarding severe riverbank erosion and flooding affecting their property along the Bigaan River in Sekyup Ilaya, Purok 3, Brgy. Gusa, Cagayan de Oro City. The condition was attributed to changes in the river's natural flow, quarrying activities, and the collapse of a riverside cave, which reportedly diverted the river toward their property and caused damage to agricultural areas. The landowner requested the conduct of dredging and excavation to restore the river's natural flow and the placement of large boulders along the affected riverbanks to prevent further erosion.

III. ACTIVITY

A joint ocular inspection and site survey were conducted at the concerned areas along the Bigaan River in Barangay Gusa, Cagayan de Oro City. The activity focused on assessing the reported riverbank erosion, changes in the river channel, and affected portions of the property.



Republic of the Philippines
City of Cagayan de Oro
**CITY DISASTER RISK REDUCTION AND
MANAGEMENT DEPARTMENT**
ORO RESCUE 911

**cagayan
de Oro**
city of golden friendship

IV. OBSERVATIONS




Based on the ocular inspection, the reported riverbank erosion and changes in the river channel were observed and may contribute to flooding and further erosion of the adjacent properties, especially during heavy rainfall.

V. STATUS OF AREA

It is recommended that a more detailed technical assessment be conducted by the appropriate concerned offices to determine the condition of the river channel and the suitability of the proposed dredging, excavation, and riverbank protection measures. Coordination with the City Engineer's Office, CLENRO, DENR, and DPWH is also recommended for proper technical evaluation and appropriate action.

In the meantime, regular monitoring of the affected area is recommended, particularly during periods of heavy rainfall and flooding, to identify any further changes in the riverbank and river flow that may pose a risk to nearby properties and residents.

VI. PICTURES and MAP



Big boulders that caused
flooding whenever there is heavy
rainfall in the said area

Lat: 8.455882°
Long: 124.685102°

Inspected by:

Jan Helton A. Ecot
Weather Watch Personnel
CDRRMD – Oro Rescue 911

Jerold Bon Lago
Drone Operator
CDRRMD – Oro Rescue 911



cagayan
de Oro
city of golden friendship



BAGONG PILIPINAS

Republic of the Philippines
CITY OF CAGAYAN DE ORO
OFFICE OF THE CITY COUNCIL
www.cdeocitycouncil.com • cdeocitycouncil@gmail.com
(088) 565-0568 • (088) 565-0697



COMMITTEE ON ENVIRONMENT

August 20, 2026

MR. NICK A. JABAGAT

City Disaster & Risk Reduction Management Officer
Cagayan de Oro City

Sir:

Acting upon the instruction of Councilor Enrico D. Salcedo, Chairperson of the Committee on Environment, City Council, this City, may we respectfully request your Office to submit to the Committee the **comments and recommendations** agreed upon during the joint ocular inspection conducted on August 5, 2026, at Sekyup Ilaya, Purok 3, Barangay Gusa, Cagayan de Oro City.

The said ocular inspection was conducted in coordination with your Office, the Office of the City Engineer, Office of the City and Natural Resources Officer, and the Department of Public Works and Highways (DPWH) 1st District Engineering Office, all of this City, in connection with the request of Mr. Reynante Namocatcat to conduct dredging and excavation operations along the Bigaan River in Barangay Gusa, with the objective of restoring its natural channel and mitigating riverbank erosion that poses a threat to nearby properties.

In this regard, we would greatly appreciate it if your Office could submit the aforementioned comments and recommendations **at the earliest possible time**, for the information and appropriate action of the Committee.

Thank you for your kind attention and prompt action on this matter.

CITY DISASTER RISK
REDUCTION & MANAGEMENT
(CDRRMD)

RECEIVED

20 AUG 2026

DATE: _____
TIME: _____
BY: _____

Very truly yours,

EILEEN JOSEPHINE L. BORJA

Board Secretary IV

Chief, Legislative Support Services Division

By Authority of HON. ENRICO D. SALCEDO, *Chairperson*