

FAO. The Court
C/o Davison Flynn Duke
Chester Street
Birkenhead
CH41 5DL

REPAIRABLE REPORT

Dear Sirs


RE: Road traffic Accident: Dr Rachael Lowton: 17/08/2022


In accordance with your instructions received on 23/08/2022 requesting us to provide an independent accident damage report, we assessed the damage on 23/08/2022. Vehicle located at Dr Rachael Lowton, Jackson Close, Bebington, Wirral. Our findings are as detailed below:

Make	FORD	Registration	M12DBL
Model	KUGA ZETEC TDCI	Status	Repair
Category		Salvage Value	
Repair Cost	£1,678.81	Legal Status	Roadworthy
Engineer Value	£3,490.00	Impact Magnitude	Light to Moderate



Impact Area





Our Ref: dfd22086

Your Ref: RJP/LOWTON

Date: 24/08/2022

NATURE OF INCIDENT

The vehicle has suffered light to moderate collision/impact damage to the rear.

ENGINEER'S COMMENTS

24/08/2022 - Mileage calculated from online MOT data.

Child's seat/travel system recommended for replacement.

VEHICLE HISTORY CHECK

24/08/2022 - According to the Experian database; there is a plate change on record

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

RESERVE

We consider that a repair reserve of £1,700.00 would be reasonable on this occasion.

Vehicle Data

Retail Value	£3,490.00
Trade Value	£1,850.00
Engineer's Value	£3,490.00
Glass's Code	FGHB
VIN	WF0RXXGCDRAS18916
Odometer	140000
Engine	1997
Fuel	Diesel
Extras	
Condition	Good
Unrelated Damage	

Main new parts required

Rear Bumper Bracket
Trailer Socket
rear bumper protection Trim

Towing Device
Sundries/clips/fixings

Repairs required

Rear Bumper Lining

Rear Bumper Spoiler

Additional operations

Check and assess reinforcement
System Diagnostic Check (Post Repair)
Car Care Kit
Environmental Charge
Paint Rear Skirt, Centre d-e
Paint Prep. synthetics (on vehicle without pre-painting)
Paint Sample colour creation (1)

Repair Method Research Allowance
System Diagnostic Check (Pre Repair)
De-Nib/Polish
Wash/Clean
Paint Rear Bumper k/d-e
Paint Colour mixing (1)

Repair Cost Calculations

Hours	7.70
Hourly Rate	£62.50
Total Labour	£481.25
Parts	£494.20
Paint/Materials	£313.56
Specialist/Other	£110.00
Sub total	£1,399.01
Vat	£279.80
Total Estimated Cost	£1,678.81



3f1cb0d0-b7ec-46cc-9c08-
27604adfca15(1).jpg



79a535c4-0769-4bb6-8cfc-
45103122a0b4.jpg



217a558a-861b-490c-bb94-
188739f8f6fb.jpg



9549bab1-3537-4a11-8779-
ac623044abe8.ipq



62501c92-51b3-4772-8bd1-
86166942b81a.jpg



c032d961-5131-44ba-baee-72b8b8122c44.jpg



e107e7e2-fac8-4769-a538-
d77ab6bce41f.jpg



f250fc31-0994-47be-a651-d2b8fc453971.jpg




f62269cf-e9c7-44d0-93d2-791e006a6de8
(1).jpg



faa14cd3-dd56-40f5-85a0-
b2432bba4881.jpg



a3011a2c-8097-4650-9107-12251c7dd61f.jpg



Our Ref: dfd22086

Your Ref: RJP/LOWTON

Date: 24/08/2022

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



A Patterson - A Patterson M.Inst.IAEA
engineers@collisionengineers.co.uk



Our Ref: dfd22086

Your Ref: RJP/LOWTON

Date: 24/08/2022

FAO. The Court
C/o Davison Flynn Duke
Chester Street
Birkenhead
CH41 5DL

Fee Note

M12DBL.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £150.00

Sub Total: £150.00

VAT: £30.00

Total Due: £180.00

Payment

Please make cheques payable to Collision Engineers and quote reference dfd22086.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o Davison Flynn Duke confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10