

Our Ref: acsp26006

Your Ref: CX58 UVS

Date: 22/01/2026

FAO The Court
C/o Accident Specialists
1-3 Brighton Road
Crawley
RH10 6AE

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Tuk Tuk Pan Asian: 19/01/2026

In accordance with your instructions received on 20/01/2026 requesting us to provide an independent accident damage report, we assessed the damage on 21/01/2026. Vehicle located at Brighton Road, Crawley, West Sussex, RH106AE. Our findings are as detailed below:


Make	VAUXHALL	Registration	CX58UVS
Model	CORSA SXI A/C AUTO	Status	T/Loss
Category	N	Salvage Value	£165.35
Repair Cost	£4,604.81	Legal Status	Unroadworthy
Engineer Value	£3,107.00	Impact Magnitude	Moderate



Impact Area



Document produced
using the EVA system



Our Ref: acsp26006

Your Ref: CX58 UVS

Date: 22/01/2026

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the left hand front.

ENGINEER'S COMMENTS

Please note the vehicle is unroadworthy due to the insecure front bumper and broken headlamp.

VEHICLE HISTORY CHECK

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

UNRELATED DAMAGE

We noted the following damage on the vehicle which does not appear to relate to the claim under review and we have therefore classed it as unrelated damage; nsr door rear bumper.

PRE-INCIDENT CONDITION


The vehicle is considered to be in average condition for its age and type.

SETTLEMENT

We consider that an equitable settlement would be £2,941.65 which represents the pre-accident engineer value of the vehicle of £3,107.00 less the value of the salvage of £165.35.

SALVAGE

Under the current salvage categorisation matrix this would be Category 'N' meaning there was no apparent structural damage evident within the scope of our inspection. Further information is available at www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £165.35. **We have not taken any action towards removal of the salvage at this time.**



Our Ref: acsp26006

Your Ref: CX58 UVS

Date: 22/01/2026

Vehicle Data

Retail Value	£3,307.00
Trade Value	£2,567.00
Engineer's Value	£3,107.00
Glass's Code	DVT9
VIN	W0L0SDL6884492190
Odometer	55887
Engine	1364
Fuel	Petrol
Extras	
Condition	Average
Unrelated Damage	nsr door

Main new parts required


Front Bumper Lining
Front Bumper Lining Clip
Front Bumper Lining Nut
Left Front Wing
Left Front Wing Repair Kit
Left Front Wing Panel Nut

Front Bumper Repair kit
Front Bumper Lining Screw
Left Headlamp, Complete (with Indicator)
Left One Front Wing and Front Bumper
Left Front Wing Panel Screw
Left Front Side Window Repair Kit

Additional operations

.Assessment Damage Appraisal Charge
.Pre repair cleaning charge
.Standard shutdown
.System Diagnostic Check (Post Repair)
.Vehicle Care Kit
Check Bonnet
NSF tyre
Paint Front Bumper
Paint Left Front Door, Complete
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)

.Environmental Charge
.QC & Road Test
.Sundries
.System Diagnostic Check (Pre Repair)
.Wash/Clean
Corrosion Protection
Wheel Alignment (check)
Paint Left Front Wing, Complete
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)



Our Ref: acsp26006


Your Ref: CX58 UVS

Date: 22/01/2026

Repair Cost Calculations

Hours	16.30
Hourly Rate	£95.77
Total Labour	£1,561.05
Parts	£910.84
Paint/Materials	£898.82
Specialist/Other	£466.63
Sub total	£3,837.34
Vat	£767.47
Total Estimated Cost	£4,604.81






Our Ref: acsp26006

Your Ref: CX58 UVS

Date: 22/01/2026






Our Ref: acsp26006

Your Ref: CX58 UVS

Date: 22/01/2026






Our Ref: acsp26006

Your Ref: CX58 UVS

Date: 22/01/2026






Our Ref: acsp26006

Your Ref: CX58 UVS

Date: 22/01/2026






Our Ref: acsp26006

Your Ref: CX58 UVS

Date: 22/01/2026






Our Ref: acsp26006

Your Ref: CX58 UVS

Date: 22/01/2026






Our Ref: acsp26006

Your Ref: CX58 UVS

Date: 22/01/2026






Our Ref: acsp26006

Your Ref: CX58 UVS

Date: 22/01/2026






Our Ref: acsp26006

Your Ref: CX58 UVS

Date: 22/01/2026





Our Ref: acsp26006

Your Ref: CX58 UVS

Date: 22/01/2026

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.

We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

A Patterson - A Patterson M.Inst.IAEA
engineers@collisionengineers.co.uk