

Date: 09/07/2025

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Mr Nirvail Singh Kang: 10/05/2025


In accordance with your instructions received on 08/07/2025 requesting us to provide an independent accident damage report, we assessed the damage on 09/07/2025. Vehicle located at Image Based Assessment. Our findings are as detailed below:

Make	FORD	Registration	FL07EOD
Model	FOCUS LX	Status	T/Loss
Category	B	Salvage Value	£17.82
Repair Cost	£8,828.27	Legal Status	Unroadworthy
Engineer Value	£891.00	Impact Magnitude	Moderate to Heavy



Impact Area





Our Ref: qdos25992

Your Ref: ZD/37835/1

Date: 09/07/2025

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate to heavy collision/impact damage to the rear, and light to moderate collision/impact to the front.

ENGINEER'S COMMENTS

09/07/2025 - Please note the vehicle is unroadworthy as the rear body has been compromised.

5/8/2025 -UPDATED REPORT: - The vehicle owner has disputed our valuation and provided some market research as evidence to dispute the same. On review of this and through conducting our own, we feel the value is £891.00

VEHICLE HISTORY CHECK

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION

The vehicle is considered to be in average condition for its age and type.

SETTLEMENT

We consider that an equitable settlement would be £873.18 which represents the pre-accident engineer value of the vehicle of £891.00 less the value of the salvage of £17.82.


SALVAGE

We consider that this is Category B (break for spares only and in-line with the ABI salvage code of practice)

This vehicle is damaged beyond any form of economical repair, therefore in our Engineers professional opinion it should not be returned to the road and a certificate of destruction should be completed / issued We suggest that the sale of the salvage will realise in the order of £17.82. **We have not taken any action towards removal of the salvage at this time.**

Vehicle Data

Retail Value	£777.00
Trade Value	£342.00
Engineer's Value	£891.00
Glass's Code	8LDY
VIN	WF05XXWPD56G30431
Odometer	148715
Engine	1596
Fuel	Petrol
Extras	
Condition	Average
Unrelated Damage	



Our Ref: qdos25992

Your Ref: ZD/37835/1

Date: 09/07/2025

Main new parts required

Rear Bumper Lining
Rear Bumper Reinforcement
Left Rear Bumper Side Bracket
Number Plate Lamp
Left Side Glass Repair/Bonding Kit
Rear Panel
Tailgate
Boot Lid/Back Door/Tailgate Striker
Boot Lid/Back Door/Tailgate Badge
Right Side Emblem (Engine Designation)

Rear Bumper Spoiler
Rear Bumper Bracket
Right Rear Bumper Side Bracket
Left Side Glass Repair/Bonding Kit
Right Side Glass Repair/Bonding Kit
Rear Panel, Outer
Latch with Central Locking
Boot Lid/Tailgate Push Button
Left Side Type Designation
Rear Window Wiper Motor

Repairs required

Front Bumper Lining

Rear Floor

Additional operations

Assessment Damage Appraisal Charge
Corrosion Protection
Energy cost supplement
Identify the presence of ADAS
Older vehicle allowance
QC & Road Test
Standard shutdown
System Diagnostic Check (Post Repair)
Vehicle Care Kit
Wheel Alignment (4 wheel)
Paint Left A-Post, Upper
Paint Left Roof Panel, Side
Paint Left Rear Side Panel, Complete
Paint Tailgate (with Window Frame)
Paint Rear Panel, Complete
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)

Boron Drill
De-nib/ polish
Environmental Charge
Load / Unload vehicle to ramp
Panel Bonding Kit
Seam Sealant
Sundries
System Diagnostic Check (Pre Repair)
Wash/Clean
Paint Front Bumper
Paint Right A-Post, Upper
Paint Right Roof Panel, Side
Paint Right Rear Side Panel, Complete
Paint Rear Floor
Paint Rear Bumper a-d
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)


Repair Cost Calculations

Hours	34.80
Hourly Rate	£80.00
Total Labour	£2,784.00
Parts	£2,278.17
Paint/Materials	£1,595.62
Specialist/Other	£699.10
Sub total	£7,356.89
Vat	£1,471.38
Total Estimated Cost	£8,828.27









Our Ref: qdos25992

Your Ref: ZD/37835/1

Date: 09/07/2025

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



A Patterson - A Patterson M.Inst.IAEA
engineers@collisionengineers.co.uk



Our Ref: qdos25992

Your Ref: ZD/37835/1

Date: 09/07/2025

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

Fee Note

FL07EOD.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £100.00

Sub Total: £100.00

VAT: £20.00

Total Due: £120.00

Payment

Please make cheques payable to Collision Engineers and quote reference qdos25992.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o QDOS Assistance confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10