

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

TOTAL LOSS REPORT

Dear Sirs



RE: Road traffic Accident: Mr Mohammad Aman: 28/06/2025


In accordance with your instructions received on 30/06/2025 requesting us to provide an independent accident damage report, we assessed the damage on 01/07/2025. Vehicle located at Image Based Assessment. Our findings are as detailed below:

Make	MITSUBISHI	Registration	KE65XTX
Model	OUTLANDER GX 3H +	Status	T/Loss
Category	N	Salvage Value	£1,634.00
Repair Cost	£7,350.73	Legal Status	Unroadworthy
Engineer Value	£8,600.00	Impact Magnitude	Moderate to Heavy



Impact Area





Our Ref: ap.qdos25945

Your Ref: /37802/1

Date: 01/07/2025

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate to heavy collision/impact damage to the left hand front.

ENGINEER'S COMMENTS

The mileage has been calculated from online MOT data.

01/07/2025 - Please note the vehicle is unroadworthy due to the extent of panel distortion sustained to the nearside front.

07/07/2025 - UPDATED REPORT: - The vehicle owner has disputed our valuation and provided some market research as evidence to dispute the same. On review of this and through conducting our own, we feel the value is £8,600.

VEHICLE HISTORY CHECK

According to the Experian database; there is a plate change on record

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

SETTLEMENT


We consider that an equitable settlement would be £6,966.00 which represents the pre-accident engineer value of the vehicle of £8,600.00 less the value of the salvage of £1,634.00.

SALVAGE

Under the current salvage categorisation matrix this would be Category 'N' meaning there was no apparent structural damage evident within the scope of our inspection. Further information is available at www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £1,634.00. **We have not taken any action towards removal of the salvage at this time.**

Vehicle Data

Retail Value	£8,270.00
Trade Value	£5,580.00
Engineer's Value	£8,600.00
Glass's Code	3BBJ
VIN	JMAXDGG2WGZ001323
Odometer	96500
Engine	1998
Fuel	
Extras	
Condition	Good
Unrelated Damage	



Our Ref: ap.qdos25945

Your Ref: /37802/1

Date: 01/07/2025

Main new parts required

Front Bumper Lining
Left Front Bumper Moulding, Side
Left Front Bumper Moulding, Side Lower
Left Front Bumper Lower Support
Left Front Bumper Side Rear Bracket
Front Bumper Repair kit
Front Bumper Lining Screw
Left Headlamp, Complete (with Indicator)
Left Front Fog Lamp, Complete
Left Front Wing Repair Kit
Left Front Wing Liner
Engine Front Guard Panel
Left Front Door Membrane

Front Bumper Reinforcement
Left Front Bumper Side Upper Moulding
Left Front Bumper H/lamp Washer Jet Flap/Lid
Left Front Bumper Plate Support
Left Front Bumper Auxiliary Lamp Cover
Front Bumper Lining Clip
Front Bumper Lining Nut
Left Headlamp Washer Jet
Left Front Wing
Left Front Wing Emblem (Letters)
Left Front Wing Panel Screw
Left Engine Rear Side Guard Panel

Additional operations


Assessment Damage Appraisal Charge
De-nib/ polish
Electric / hybrid shutdown and power up
Environmental Charge
QC & Road Test
Sundries
System Diagnostic Check (Pre Repair)
Wash/Clean
Paint Front Bumper a-d/k
Paint Right Front Wing, Complete
Paint Left A-Post, Upper
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)

Corrosion Protection
Electric / hybrid risk assessment
Energy cost supplement
Identify the presence of ADAS
Repair method research charge
System Diagnostic Check (Post Repair)
Vehicle Care Kit
Wheel Alignment (4 wheel)
Paint Left Front Wing, Complete
Paint Bonnet
Paint Left Front Door, Complete
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)


Repair Cost Calculations

Hours	19.40
Hourly Rate	£80.00
Total Labour	£1,552.00
Parts	£3,046.71
Paint/Materials	£921.92
Specialist/Other	£604.98
Sub total	£6,125.61
Vat	£1,225.12
Total Estimated Cost	£7,350.73









Our Ref: ap.qdos25945

Your Ref: /37802/1

Date: 01/07/2025

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



A Patterson - A Patterson M.Inst.IAEA
engineers@collisionengineers.co.uk



Our Ref: ap.qdos25945

Your Ref: /37802/1

Date: 01/07/2025

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

Fee Note

KE65XTX.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £100.00

Sub Total: £100.00

VAT: £20.00

Total Due: £120.00

Payment

Please make cheques payable to Collision Engineers and quote reference ap.qdos25945.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o QDOS Assistance confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10