

FAO The Court

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Mr Serhan Eser: 12/05/2026


In accordance with your instructions received on 19/05/2026 requesting us to provide an independent accident damage report, we assessed the damage on 19/05/2026. Vehicle located at Image-based Assessment. Our findings are as detailed below:

Make	LAND ROVER	Registration	WF66ULA
Model	R ROVER SPORT HSE D	Status	T/Loss
Category	N	Salvage Value	£1,404.60
Repair Cost	£15,189.01	Legal Status	Unroadworthy
Engineer Value	£14,046.00	Impact Magnitude	Moderate to Heavy



Impact Area





Our Ref: pch261076

Your Ref: 576155

Date: 19/05/2026

NATURE OF INCIDENT

The vehicle has suffered moderate to heavy collision/impact damage to the left hand side.

ENGINEER'S COMMENTS

The mileage has been calculated from online MOT data.

20% has been deducted from the pre accident valuation due to the vehicle being a previous total loss.

This is a non genuine front bumper we believe it possibly an lumma bumper

Please be aware Land Rover do not recommend repairing the alloy wheels.

The vehicle is unroadworthy due to the impacted wheel and tyre

VEHICLE HISTORY CHECK

According to the Experian database; there is a plate change on record See the plate change details. Category N total loss claim Non Structural Damage See the Condition details An entry exists on the MIAFTR register to this effect dated 08/04/2025, loss dated 23/11/2024

PRE-INCIDENT CONDITION


The vehicle is considered to be in good condition for its age and type.

SETTLEMENT

We consider that an equitable settlement would be £12,641.40 which represents the pre-accident engineer value of the vehicle of £14,046.00 less the value of the salvage of £1,404.60.

SALVAGE

Under the current salvage categorisation matrix this would be Category 'N' meaning there was no apparent structural damage evident within the scope of our inspection. Further information is available at www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £1,404.60. **We have not taken any action towards removal of the salvage at this time.**



Our Ref: pch261076

Your Ref: 576155

Date: 19/05/2026

Vehicle Data

Retail Value	£17,557.00
Trade Value	£14,045.00
Engineer's Value	£14,046.00
Glass's Code	MFTR
VIN	SALWA2KE6GA113542
Odometer	81855
Engine	2993
Fuel	Diesel
Extras	
Condition	Good

Main new parts required


Front Bumper
Frt Bumper Clamp Kit
Screw M6 X 22Mm
R/Bonnet Badge
L/F Wing
L/F Door Lwr Mldg
L/F Door Clamp Kit
L/R Door Trim Foil
L/Side Park Sensor
L/F Tyre
L/F Inf Press Sensor
L/R Tpc Aerial
Sundry Parts

L/F Bmper Brkt Plate
Clip Fastening
L/Bonnet Badge
Bonnet Insulation
L/Lower Wing Trim
L/F Door Trim Foil
L/R Door Lwr Mldg
Screw
L/F Wheel
Tyre Press Receiver
L/R Inf Press Sensor
L/R Wheel

Repairs required

L/F Lower Door
Rear Bumper

L/R Door Lower



Our Ref: pch261076

Your Ref: 576155

Date: 19/05/2026


Additional operations

Check Miracle Pull Set Up
 Paint Front Bumper New Part Paint K1r
 Paint L/F Door Lwr Mldg New Part Paint K1r
 Paint L/Side Park Sensor New Part Paint K1r
 Paint L/R Door Lower Repair Painting <50%
 Blend Bonnet Surface Paint
 Blend L/F Door Out Handle Surface Paint Plast.
 Blend L/R Door Out Handle Surface Paint Plast.
 Paint Preparation For Pre-Painting
 Assessment Fee
 Vehicle Care Kit
 Delivery To Client Returning Veh

Paint L/F Wing New Part Painting
 Paint L/Lower Wing Trim New Part Paint K1r
 Paint L/R Door Lwr Mldg New Part Paint K1r
 Paint L/F Lower Door Repair Painting <50%
 Paint Rear Bumper Repair Paint Plastic
 Blend R/F Wing Surface Paint
 Blend L/Door Handle Cover Surface Paint Plast.
 Paint Denib / Polish Paint
 Wheel Alignment
 Epa Charge
 Paint Consumable
 Corrosion Mat

Repair Cost Calculations

Hours	43.50
Hourly Rate	£95.77
Total Labour	£4,166.00
Parts	£6,042.93
Paint/Materials	£1,916.85
Specialist/Other	£531.74
Sub total	£12,657.51
Vat	£2,531.50
Total Estimated Cost	£15,189.01




Our Ref: pch261076

Your Ref: 576155

Date: 19/05/2026








Our Ref: pch261076

Your Ref: 576155

Date: 19/05/2026





Our Ref: pch261076

Your Ref: 576155

Date: 19/05/2026









**COLLISION
ENGINEERS**


INDEPENDENT AUTOMOTIVE EXPERTS

Our Ref: pch261076

Your Ref: 576155

Date: 19/05/2026





Our Ref: pch261076

Your Ref: 576155

Date: 19/05/2026

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully

N O'Reilly - ATA VDA

engineers@collisionengineers.co.uk



Our Ref: pch261076

Your Ref: 576155

Date: 19/05/2026

FAO The Court

Fee Note

WF66ULA.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £150.00

Sub Total: £150.00

VAT: £30.00

Total Due: £180.00

Payment

Please make cheques payable to Collision Engineers and quote reference pch261076.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10