

Our Ref: qdos221398

Your Ref: CJH/14169/1

Date: 23/08/2022

FAO The Court
C/o QDOS Assistance
1st Floor, Barfield House
24-28 Alderly Road
SK91PL

REPAIRABLE REPORT

Dear Sirs


RE: Road traffic Accident: Jeffery Clayton: 07/08/2022

In accordance with your instructions received on 12/08/2022 requesting us to provide an independent accident damage report, we assessed the damage on 23/08/2022. Vehicle located at Image based assessment. Our findings are as detailed below:


Make	MERCEDES-BENZ	Registration	J77EVR
Model	C250 AMG LINE PREM	Status	Repair
Category		Salvage Value	
Repair Cost	£10,541.75	Legal Status	Unroadworthy
Engineer Value	£20,136.00	Impact Magnitude	Moderate



Impact Area



Document produced
using the EVA system



Our Ref: qdos221398

Your Ref: CJH/14169/1

Date: 23/08/2022

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the right hand side.

ENGINEER'S COMMENTS

Mileage calculated from on line MOT data.

23/08/2022 - Please note the vehicle is unroadworthy due to the broken offside mirror and steering fault.

We understand the repairer is NON VAT registered so will not be invoicing VAT on the labour.

VEHICLE HISTORY CHECK

23/08/2022 - According to the Experian database; there is a plate change on record See the plate change details. Category S total loss claim Structural Damage See the Condition details An entry exists on the MIAFTR register to this effect dated 13/12/2021, loss dated 03/08/2020

PRE-INCIDENT CONDITION


The vehicle is considered to be in good condition for its age and type.

RESERVE

We consider that a repair reserve of £10,550.00 would be reasonable on this occasion.

Vehicle Data

Retail Value	£25,170.00
Trade Value	£22,630.00
Engineer's Value	£20,136.00
Glass's Code	7BGW
VIN	WDD2053092F492609
Odometer	30000
Engine	2143
Fuel	Diesel
Extras	
Condition	Good
Unrelated Damage	



Our Ref: qdos221398

Your Ref: CJH/14169/1

Date: 23/08/2022

Main new parts required

Right LED Headlamp (with indicator)
Right Front Wing Repair Kit
Right Front Wing Liner, Front
Right Front Wing Panel Screw
Bonnet Badge
Right Front Door Ext Mirror (Elect/Htd)
Right F. Door Exterior Mirror Adjusting Motor
Right Exterior Mirror Side Repeater Lamp
Left Front Wheel (Aluminium)
Front Wheel Kit (2 Pieces)

Right Front Wing
Right Front Wing Badge
Right Front Wing Liner, Rear
Right Front Wing Panel Nut
Right Front Door Window Outer Channel Strip
Right Front Door Exterior Mirror Cover
Right Ext Mirror Glass (Elec/Htd/Auto Dim)
Power Steering Rack Assembly
Right Front Wheel (Aluminium)
Right Front Door Trim Support Kit

Repairs required

Right Front Door Shell

Additional operations

Repair Method Research Allowance
System Diagnostic Check (Pre Repair)
Check and adjust four wheel alignment
Environmental Charge
Tyre
Adjust headlamps
Paint Right Front Wing, Complete
Paint Right A-Post, Upper
Paint Right Front Door Outer Handle
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)

System Diagnostic Check (Post Repair)
Car Care Kit
De-Nib/Polish
Final Inspection & Road Test
Wash/Clean
Paint Front Bumper
Paint Bonnet
Paint Right Front Door, Complete F
Paint Right Rear Side Panel, Complete
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)

Repair Cost Calculations

Hours	22.10
Hourly Rate	£62.50
Total Labour	£1,381.25
Parts	£5,844.10
Paint/Materials	£1,154.44
Specialist/Other	£405.00
Sub total	£8,784.79
Vat	£1,756.96
Total Estimated Cost	£10,541.75