

Our Ref: ggp22073

Your Ref: 102397.002/RY/R
Y

Date: 24/08/2022

FAO The Court
C/o Graham Coffey & Co
1st Floor, Faulkner House
Faulkner Street
Manchester
M1 4DY

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: Focus UK One Ltd: 20/08/2022


In accordance with your instructions received on 23/08/2022 requesting us to provide an independent accident damage report, we assessed the damage on 24/08/2022. Vehicle located at Swade Storage, Meek Street, Royton, OL2. Our findings are as detailed below:

Make	SKODA	Registration	DK66LRL
Model	OCTAVIA SE L TDI	Status	T/Loss
Category	S	Salvage Value	£680.00
Repair Cost	£9,148.07	Legal Status	Unroadworthy
Engineer Value	£6,800.00	Impact Magnitude	Moderate to Heavy



Impact Area





Our Ref: ggp22073

Your Ref: 102397.002/RY/R
Y

Date: 24/08/2022

NATURE OF INCIDENT

The vehicle has suffered moderate to heavy collision/impact damage to the right hand side.

ENGINEER'S COMMENTS

24/08/2022 - Please note the vehicle is unroadworthy due to the extent of panel distortion sustained to the offside. Mileage calculated from on line MOT data.

VEHICLE HISTORY CHECK

24/08/2022 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

SETTLEMENT


We consider that an equitable settlement would be £6,120.00 which represents the pre-accident engineer value of the vehicle of £6,800.00 less the value of the salvage of £680.00.

SALVAGE

Under the current salvage categorisation matrix, **within the scope of our inspection**, we consider that this is Category S, (Structural damage) and can be sold as repairable salvage. Further information is available www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £680.00.
We have not taken any action towards removal of the salvage at this time.

Vehicle Data

Retail Value	£6,800.00
Trade Value	£4,710.00
Engineer's Value	£6,800.00
Glass's Code	DGYB
VIN	TMBKG7NE3G0270657
Odometer	150000
Engine	1598
Fuel	Diesel
Extras	
Condition	Good
Unrelated Damage	



Our Ref: ggp22073

Your Ref: 102397.002/R/Y/R
Y

Date: 24/08/2022

Main new parts required

Right Front Wing
 Right Front Wing Insulation
 Right Front Wing Foam
 Right Front Wing Panel Nut
 Right Bonnet Side Seal
 Right Front Door Shell
 Right Front Door Window Outer Channel Strip
 Right Front Door Insulation
 Right Rear Door Outer Weatherstrip
 Right Rear Door Insulation
 Right Roof Side Airbag
 Right Rear Side Panel Bonding Kit
 Right Rear Side Glass Primer
 Right Rear Side Glass Activator
 Right Side Panel Foam
 Right A-Post Upper Interior Trim
 Headlining
 Right Front Door Trim Clip
 Right Rear Door Trim Clip

Right Front Wing Repair Kit
 Right Front Wing Liner
 Right Front Wing Panel Screw
 Left Bonnet Side Seal
 Bonnet Badge
 Right Front Door Outer Seal
 Right F. Door Exterior Mirror Housing (Elec)
 Right Rear Door Shell
 Right Rear Door Outer Window Channel Strip
 Right Sill Panel
 Right Rear Side Panel
 Right Side Glass Repair/Bonding Kit
 Right Rear Side Glass Applicator
 Right Side Panel Insulation
 Right Side Panel Liner
 Right B-Post Upper Interior Trim
 Right Front Door Trim Support Kit
 Right Rear Door Trim Support Kit

Additional operations

Jig set up, clamp and pull
 System Diagnostic Check (Post Repair)
 Car Care Kit
 De-Nib/Polish
 Final Inspection & Road Test
 Wash/Clean
 Paint Right Front Wing, Complete
 Paint Right Front Door, Complete
 Paint Right Rear Door, Complete
 Paint Right Rear Side Panel, Complete
 Paint Prep. metal (on vehicle without pre-painting)
 Paint Colour mixing (1)


Repair Method Research Allowance
 System Diagnostic Check (Pre Repair)
 Check and adjust four wheel alignment
 Environmental Charge
 Tyre
 Paint Front Bumper
 Paint Bonnet
 Paint Right Front Door Outer Handle
 Paint Right Sill Panel, Outer
 Paint Rear Bumper k/e
 Paint Prep. synthetics (combined-operation work)
 Paint Sample colour creation (1)

Repair Cost Calculations

Hours	45.80
Hourly Rate	£62.50
Total Labour	£2,862.50
Parts	£2,731.15
Paint/Materials	£1,724.74
Specialist/Other	£305.00
Sub total	£7,623.39
Vat	£1,524.68
Total Estimated Cost	£9,148.07



5b443a01-2540-4e98-a540-
935fc71071b3.jpg



Our Ref: ggp22073

Your Ref: 102397.002/RY/R
Y


Date: 24/08/2022



7b00612b-aa4f-4c87-9982-
6ff465f9b945.jpg



969ae164-fe0a-463e-90af-
9def895b3254(1).jpg



Our Ref: ggp22073

Your Ref: 102397.002/RY/R
Y

Date: 24/08/2022



84413411-a4ef-4065-9327-
121a722561d8.jpg




b7b09f91-1ef1-4bb2-80c8-
9f64bcc03c38.jpg



bdb2f74-0bde-4288-8039-
df1eb09341b9(1).jpg



c3613933-b5dd-4d72-9093-
265f5d6a3e49.jpg




Our Ref: ggp22073

Your Ref: 102397.002/RY/R
Y

Date: 24/08/2022



f7e6dde0-0d48-4c19-ac22-
4a400dc19511.jpg



Our Ref: ggp22073

Your Ref: 102397.002/RY/R
Y

Date: 24/08/2022

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



A Patterson - A Patterson M.Inst.IAEA
engineers@collisionengineers.co.uk



Our Ref: ggp22073

Your Ref: 102397.002/RY/R
Y

Date: 24/08/2022

FAO The Court
C/o Graham Coffey & Co
1st Floor, Faulkner House
Faulkner Street
Manchester
M1 4DY

Fee Note

DK66LRL.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £150.00

Sub Total: £150.00

VAT: £30.00

Total Due: £180.00

Payment

Please make cheques payable to Collision Engineers and quote reference ggp22073.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/o Graham Coffey & Co confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10