

FAO The Court
C/O Blackstone Legal
Unit 18, Gillington Road
Bradford
BD8 9NL

TOTAL LOSS REPORT

Dear Sirs


RE: Road traffic Accident: MD Islam: 10/12/2024


In accordance with your instructions received on 15/12/2024 requesting us to provide an independent accident damage report, we assessed the damage on 17/12/2024. Vehicle located at Lodge Road, West Bromwich, West Midlands, B70 8NX. Our findings are as detailed below:

Make	NISSAN	Registration	OU06YHC
Model	NOTE SVE	Status	T/Loss
Category	N	Salvage Value	£62.50
Repair Cost	£2,625.49	Legal Status	Unroadworthy
Engineer Value	£1,250.00	Impact Magnitude	Moderate



Impact Area





Our Ref: black24076

Your Ref: SA:24300SA

Date: 17/12/2024

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the left hand side.

ENGINEER'S COMMENTS

17/12/2024 - Please note the vehicle is unroadworthy due to the broken rear bumper.

31/12/2024 - UPDATED REPORT: - The vehicle owner has disputed our valuation and provided some market research as evidence to dispute the same. On review of this and through conducting our own, we feel the value is £1250.00

VEHICLE HISTORY CHECK

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

UNRELATED DAMAGE

We noted the following damage on the vehicle which does not appear to relate to the claim under review and we have therefore classed it as unrelated damage; all over.

PRE-INCIDENT CONDITION

The vehicle is considered to be in very poor condition for its age and type.

SETTLEMENT


We consider that an equitable settlement would be £1,187.50 which represents the pre-accident engineer value of the vehicle of £1,250.00 less the value of the salvage of £62.50.

SALVAGE

Under the current salvage categorisation matrix this would be Category 'N' meaning there was no apparent structural damage evident within the scope of our inspection. Further information is available at www.abi.org.uk. We suggest that the sale of the salvage will realise in the order of £62.50. **We have not taken any action towards removal of the salvage at this time.**

Vehicle Data

Retail Value	
Trade Value	
Engineer's Value	£1,250.00
Glass's Code	KTWY
VIN	SJNFCAE11U1010317
Odometer	83297
Engine	1598
Fuel	Petrol
Extras	
Condition	Very Poor
Unrelated Damage	all over



Our Ref: black24076

Your Ref: SA:24300SA

Date: 17/12/2024

Main new parts required

Rear Bumper Lining
Rear Bumper Repair Kit
Rear Bumper Lining Screw
Right Rear Panel Side Trim

Rear Bumper Impact Absorber/Filler
Rear Bumper Lining Clip
Rear bumper lining Nut

Additional operations

De-nib/ polish
Environmental Charge
QC & Road Test
System Diagnostic Check (Post Repair)
Wash/Clean
Paint Right Rear Side Panel, Complete
Paint Right Rear Cover, Side (below Rear Lamps)
Paint Prep. metal (on vehicle without pre-painting)
Paint Colour mixing (1)
Set-up time


Energy cost supplement
Estimate/Assessment Charge
Research Methods
System Diagnostic Check (Pre Repair)
Paint Left Rear Side Panel, Complete
Paint Right Fuel Filler Lid
Paint Rear Bumper k/b
Paint Prep. synthetics (combined-operation work)
Paint Sample colour creation (1)

Repair Cost Calculations

Hours	10.20
Hourly Rate	£80.00
Total Labour	£816.00
Parts	£381.51
Paint/Materials	£637.40
Specialist/Other	£353.00
Sub total	£2,187.91
Vat	£437.58
Total Estimated Cost	£2,625.49








Our Ref: black24076

Your Ref: SA:24300SA

Date: 17/12/2024







Our Ref: black24076
Your Ref: SA:24300SA


Date: 17/12/2024












Our Ref: black24076

Your Ref: SA:24300SA

Date: 17/12/2024





Our Ref: black24076

Your Ref: SA:24300SA

Date: 17/12/2024

Statement of Truth

I declare that I understand my duty in providing this report to the court and I confirm that I have complied with that duty. I understand that this duty overrides any other obligation. The report is based upon instructions received.

I confirm that I have made clear facts and matters referred to in this report are within my own knowledge and which are not. Those are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinion on the matters to which they refer.


We have used Glass's Evaluator to assist with the valuation of the vehicle and Thatcham and / or manufactures data to compile the repair specification. Parts prices are subject to fluctuations and further damage may be found upon dismantling the vehicle. Our valuation is based on the mileage information provided and assuming that the vehicle has a valid MOT certificate (where applicable) to support such.

We appreciate your instructions and enclose our fee note for your kind attention, which we confirm remains payable irrespective of the outcome of this case. Please ensure this is passed to your accounts department.

Yours faithfully



A Patterson - A Patterson M.Inst.IAEA
engineers@collisionengineers.co.uk



Our Ref: black24076

Your Ref: SA:24300SA

Date: 17/12/2024

FAO The Court
C/O Blackstone Legal
Unit 18, Girlington Road
Bradford
BD8 9NL

Fee Note

OU06YHC.

Collate data, compile repair specification, calculate estimate, research valuation.

Produce Vehicle Damage Assessment report.

Storage of all material case files and images.

Agreed Fee: £150.00

Sub Total: £150.00

VAT: £30.00

Total Due: £180.00

Payment

Please make cheques payable to Collision Engineers and quote reference black24076.

Collision Engineers, 77-79 Hoylake Road, Moreton, Wirral, CH46 9PY.

This is not a tax invoice – a receipted invoice will follow upon payment. We will not accept any reduction to our fee through the detailed assessment process.

Any requests for addendum reports or letters including those required for clarification, plus Counsel, Court or other meetings will be subject to a further charge & subject to Civil Procedure Rule 35.6.

Terms: As per this agreement, following which we reserve the right to claim statutory interest at 8% above the Bank of England reference rate in force on the date the debt becomes overdue and at any subsequent rate where the reference rate changes and the debt remains unpaid in accordance with the Late Payment of Commercial Debts (Interest) Act 1998 as amended and supplemented by the Late Payment of Commercial Debts Regulations 2002. Payment is due in full within 89 days from the date of this report unless otherwise stated. In addition, for unpaid debts up to £999.99 we are allowed to claim compensation of £40.00.

C/O Blackstone Legal confirm to be liable for the charges of this report and any subsequent addendum reports on acceptance of this report by electronic mail. If you do not so wish to be bound by these terms you must reject the report and confirm so immediately.

Vat number: 262 0937 10